DIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

December 4, 1964

Tenneco 011 Company P.O. Box 1714 Durango, Colorado

Re: Tenneco #4 Moore, H-5-30N-8W
Blanco Mesaverde Pool

Centlemen:

The above well was acquired by your company recently from Delhi-Taylor Oil Company. It has come to our attention from the annual deliverability test which was filed with this office by Delhi-Taylor prior to the transfer that casing failure has occurred in this well. This fact is indicated by the abnormally low shut-in pressure of 580# and also by the flow rate which is about 1 of the flow rate of the previous year's annual deliverability test.

You are, therefore, directed to take immediate remedial action to repair the casing in this well in order to prevent the waste of gas reserves from the Blanco Mesaverde reservoir. Please submit Form C-102 to this office setting out your remedial plan prior to commencement of operations.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA : ks

cc: Oil Conservation Commission Santa Ps, New Mexico

OIL CONSERVATION COMMISSION

IDDO RID ƏKAZDƏ ROND AZTEÇ, NSW MEXICO

PROPERTY OF A RESERVE

iges of the state of the state

Ace Might et al. 1900 but began in the little of the littl

នៃក្រុម ប្រជាពី នៅក្រុម ប្រជាពី ប្រជាពី ប្រជាពី ប្រជាពី ប្រជាពី ប្រជាពី ប្រជាពី នៅ ប្រើបាន នៅ ប្រជាពី ប្រជាព

The state of the s

প্ৰসংগ্ৰহ ১৮ চুৰ্বজন্ম এই ইন্ডিট ১৮৮৮ চুক্ৰ **ইপড়েব্ৰেড**

TELENOMEN TO CONTRACT TO THE