

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E-505-6

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name N E Blanco Unit Agrmt. No. 1, Sec. 929
2. Name of Operator Blackwood & Nichols Company	8. Farm or Lease Name N E Blanco Unit
3. Address of Operator P.O. Box 1237, Durango, Colorado 81301	9. Well No. 21
4. Location of Well UNIT LETTER N 990 FEET FROM THE S LINE AND 1800 FEET FROM THE W LINE, SECTION 36 TOWNSHIP 31N RANGE 7W NMPM.	10. Field and Pool, or Wildcat Blanco Mesaverde
15. Elevation (Show whether DF, RT, GR, etc.) GR 6475'	12. County Rio Arriba

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Pull 2 3/8" tubing, set bridge plug in 5 1/2" liner, locate holes in 7" casing, squeeze cement, drill cement and plugs, clean out well with gas. Rerun tubing and return well to production.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by DeLasso Loos	DeLasso Loos	TITLE Field Superintendent	DATE 3/21/72
APPROVED BY <i>Curry</i>	TITLE <i>Sup Int III</i>	DATE 3-23-72	

CONDITIONS OF APPROVAL, IF ANY: