In Lieu o		ED STATES ENT OF INTERIOR	FORM APPROVED	
(June 199	Μ)		Budget Bureau No. 1004-0135 Expires: March 31, 1993	
SUNDRY NOTICE AND Do not use this form for proposals to drill or to deepen TO DRILL" for perm		REPORTS ON WELLS L.M. Or reenty to a different reservoir. Use "APPLICATION nit for such proposals SEP 24 PILLS MM	5. Lease Designation and Serial No. SF-079165	
			6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation ROSA UNIT		
1.	Type of Well ☐ Oil Well ☐ Gas Well ☐	□ Other	8. Well Name and No. ROSA UNIT #15	
2.	Name of Operator WILLIAMS PRODUCTION COMPANY		9. API Well No. 30-039-07946	
3.	Address and Telephone No. PO BOX 3102 MS 37-4, TULSA, OK 74101	(918) 588-4592	10. Field and Pool, or Exploratory Area BLANCO MV	
4.	Location of Well (Footage, Sec., T., R., M., o 1680' FNL & 1110' FEL, SE/4 NE/4 SEC 29-		11. County or Parish, State RIO ARRIBA, NM	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			PORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION		
	■ Notice of Intent □ Subsequent Report	 □ Abandonment □ Recompletion □ Plugging Back ■ Casing Repair 	☐ Change of Plans ☐ New Construction ☐ Non-Routine Fracturing ☐ Water Shut-Off	
	☐ Final Abandonment	□ Altering Casing □ Other	☐ Conversion to Injection ☐ Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
13.	Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*			
A rig will be moving on this well September 22, 1998. Casing integrity will be checked and repaired if a problem is found. Procedure is attached.				
	•			
	DEGERMED.			
			000 000	
		all con div		
			्राष्ट्रमान् वर्षः	
14.	I hereby certify that the foregoing is true and	correct		
	Signed SUSAN GRIGUHN 5 Grace	Title CLERK D	Pate September 21, 1998	
	(This space for Federal or State office use) S/ Duane W. Specific Approved by	Title	SEP 2.8 1998	
	Conditions of approval, if any:			
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.				

WILLIAMS PRODUCTION COMPANY ROSA UNIT #15

Purpose: To locate and repair possible casing leak.

- Check location and rig anchors.
 Dig a small circulation pit.
 Locate and test anchors. Set new anchors if necessary.
 Notify BLM prior to moving in.
- 2. MIRUSU. Nipple up and test BOP, stripping head, blooie line, working valves and 2" relief line.
- 3. Blow down well. Kill with produced water if necessary
- 4. Pull donut. RIH to TD at 5913' and check for fill. Bring out additional tbg if needed. TOH with 2-3/8" tubing. Check tbg and replace any bad jts.
- 5. Set RBP above perfs in 5" casing. Pressure test casing to 800 psi. locate csg leak if pressure doesn't. Load hole hole with produced water.
- 6. When leak is isolated, pump into it and establish a rate.
- Squeeze below packer with Class "B" cement. Set pkr at least 100' above hole. Conditions and depth will determine additives.
 Hesitate last few sx cement below tbg to build pressure. S.I. overnight.
- 8. Drill out cement. Pressure test to 800 psi. TOH with tbg and packer.
- 9. TIH and retrive RBP.
- 10. TIH with 2-3/8", 4.7#, J-55, 8rd, EUE tbg and land at \pm 5850'.
- 11. Swab well in if necessary.
- 12. ND BOP and NU wellhead.
- 13. Clean up location and release rig.

Sterg	Katirgis
Sr. Er	naineer