




STATE OF NEW MEXICO
ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE



BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

April 29, 1992

Mr. Mike Turnbaugh
Northwest Pipeline Corporation
3539 E. 30th St.
Farmington, NM 87401

RE: Rosa Unit #94, K-16-31N-5W

Dear Mr. Turnbaugh:

On April 16, this office conducted a field inspection of the Rosa Unit #94 to determine the injection and annular pressures at the wellhead. The pressures could not be determined because all of the gauges were broken.

Pursuant to Rule 701-B-1 and Order No. R-8685, a pressure gauge or approved leak-detection device should be attached to the annulus in order to determine leakage in the casing, tubing or packer. The injection well should also be equipped with a pressure-limiting switch or other acceptable device which will limit the wellhead pressure on the injection well to no more than 1072 psi.

You are required to repair or replace these gauges immediately to prevent shut-in of this well.

If you have any questions please feel free to contact this office.

Yours truly,

Dianna Fairhurst

Dianna Fairhurst
Deputy Oil and Gas Inspector

XC: OPERATOR FILE
UIC FILE
DKF FILE