District 1 - (505) 393-6161 1625 N. French Dr Hobbs, NM 88240 District 11 - (505) 748-1283 811 S. Fir.i Artesia, NM 88210 District 111 - (505) 334-6178 1000 Rio Brazos Road Aztec, NM 8710 District 1V - (505) 827-7131 2040 S. Pacheco Santa Fe, NM 87505		New Mex and Natural Conservation 2040 South Pache anta Fe, New Mex (505) 827-7 APPLICATION	Resources D n Division co Street sico 87505 131	eparture 118 2	Form C-140 Revised 06/99 SUBMIT ORIGINAL PLUS 2 COPIES TO APPROPRIATE DISTRICT OFFICE
	WE	LL WORKOVER	PROJECT		
I. Operator and Wel Operator name & address Williams Producti		<u> </u>		OGRIPHU	120782
P.O. Box 3102 Tulsa, OK 74101				Phone	
Contact Party Kristine Russell				918/	/573-6181
Property Name			Well Numb 232	er API Numb 30-0	er 39-24643
Rosa Unit	Range Feet From The	North/South Line	Feet From The 985 '	East/West Line West	County Rio Arriba
M 20 31N	5W 1310'	South			
II. Workover Date Workover Commenced: 10/24/1999 Date Workover Completed:	Previous Producing Pool(s) (I	Prior to Workover):			
III. Attach a descript IV. Attach a producti least three month	ion of the Workover Proc ion decline curve or table hs of production following				ior to the workover and at crease.
2. I have m Well. 3. To the b for this v	sa) ss. e11, being first duly coperator, or authorized hade, or caused to be ma best of my knowledge, this Well are complete and ac well are complete and ac well are complete me this	representative o ide, a diligent se s application and courate.	the Operator, o arch of the produ the data used to <u>ction Analys</u> <u>June</u> , d	o prepare the pr	erenced Well. easonably available for this roduction curve and/or table ate <u>6/23/2000</u>
FOR OIL CONSERVATIO VI. CERTIFICATIO This Application Division hereby	ON DIVISION USE ONLY: ON OF APPROVAL: n is hereby approved and	Department of th	his Approval and	certifies that thi	Workover Project and the he Division notifies the s Well Workover Project was
Signature District Supervisor	35.7		istrict	Date 9/1/0	೧ಎ

DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT: VII.

.

ب بر					
•	- STATE OF	NEW MEXICO	·		
ENERC	Y, MINERALS AND NA	TURAL RESOURCES DEPAR	TMEN I Form C		
., 4	OUL CONSERV	ATION DIVISION	Revised 1-		
	OIL CONSERV	A RUIDIN DI VIDIOIN			
	AZTE	RÁŽOS RD. Č. NM 87410			
mit 3 copies to	16 - 18	89			
propriate District Office	IN NON JO				
STRICT 1	elijos na	WELL API NO. 30-039-24643			
P O Box 1980, Hobbs, NM 88240 DISTRICT 2 P O Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease STATE Γ FEE ■			
STRICT 3 OO Rio Brazos Rd., Aztec, NM 87410	-	6. State Oil & Gas Lease No.			
		7. Lease Nume or Unit	Agreement Name		
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR	PROPOSALS TO DRILL OK TO	ROSA UNIT			
DEEDEN OF PLUC BACK TO A	DIFFERENT RESERVOIR. USE T" (FORM C-101) FOR SUCH				
PROPO	SALS)				
Type of Well GAS WELL >	COTHER				
. Name of Operator		B. Well No.			
WILLIAMS PRODUCTION	COMPANY	232			
Address of Operator P O BOX 3102, MS: 37-2,	TULSA, OK 74101	9. Pool Nunz or Wildent BASIN FRUITLAND COAL			
4. Well Location Unit Letter <u>M</u> : <u>1310</u> Feet 1	From The <u>SOUTH</u> Line and <u>985</u> Feet				
Section 20 Township 31N R	ange <u>5W</u> NMPM <u>RIO ARRI</u>				
		10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6330' KB			
	CHECK APPROPRIATE BOX TO INDICA	TE NATURE OF NOTICE, REPORT, OR OTHER DATA			
NOTICE OF	INTENTION TO:	SUBSEQUEN			
PERFORM REMEDIAL WORK	NDONABANDON CHANGE FLANS	REMEDIAL WORK COMMENCE DRILLING OPINIONS	ALTERING CASING PLUG AND ABANDONMENT		
TEMPORARILY ABANDON PULL OR ALTER CASING	OTHER	CASING TEST AND CEMENT JOB	OTHER <u>CAVITATION</u>		
12. Describe Proposed or Completed C	Operations (Clearly state all pertisent details, and give g	pertinent dates, including estimated date of sturing any proposed	d work) SEE RULE 1103.		
in hole w/ mill		oie lines, pressure test, strap tubing o			
3050'-3130'		w/ spear, spear liner, COOH, LD liner,			
10-26-1999 Underream to 31 hvy 1/8" coal to fines in dark	98', circulate hole clean, COOH, gray wtr reducing to lite coal, dry	LD underreamer, TIH w/ 6 1/4" bit, tag well, flow test73 mcfd, pressure up	@ 3071', CO 3071'-3198', returns- w/ air for 1 st surge		
	Ca	ntinued on reverse side			
I hereby certify that the information above is tru	e and complete to the best of my knowledge and belief.				
	TITLE_PRODUCTION		DATE November 10, 1999		
TYPE OR PRINT NAME TRACY RO	ISS TELEPHO	NE NO. <u>918/573-6254</u>	· · · · · · · · · · · · · · · · · · ·		
(This space for State Use)	INED BY CHARLIE T. PERMIN	DEPUTY OIL & GAS INSPECTOR, I	DIST. # NOV 1 6 199		
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:					
4					

s , s ...

10-28-1999 CO @ 3198', returns-hvy reducing to lite 14" coal and shale (90/10) to fines in black to dark gray wtr, dry well, flow test-145 mcfd, pressure up to surge

10-29-1999 Surge 8 times w/ air and wtr to 1900 psi, (1 – 1 ½ hr build), returns-hvy coal, gas and wtr, last three surges bridged off, TIH, tag @ 2936', cleaning out bridges, CO 3116'-3146' w/ 1800 scf air and 5 – 10 bph mist, returns-hvy ½" coal in black wtr

10-30-1999 CO 3116'-3178' w/ 1800 – 900 scf air and 10 – 5 bph mist, returns-hvy 1/4" coal and shale (90/10) to fines in black wtr, rig repair, TIH, tag @ 3140', CO 3140'-3196', returns-hvy reducing to med 1/4" coal and shale (90/10) to fines in black to gray wtr

10-31-1999 CO 3176'-3196', returns-lite 1/4" coal and shale (90/10) to fines in gray wtr, dry well, flow test—189 mcfd, COOH to DC's, surge 9 times w/ air and mist to 1600 psi, returns-hvy coal, gas and black wtr

11-01-1999 Surge 2 times w/ air and mist to 1800 psi, returns-med coal, black wtr and gas, TIH, tag @ 2733, CO bridges to 3024', CO 3024'-3157', returns-hvy ½" coal and small shale (95/05) to fines in black wtr, hole got tight, had to LD and PU 2 jts several times

11-02-1999 CO @ 3198', returns-hvy 14" coal and small shale (95/05) to fines in black wtr

11-03-1999 CO @ 3198'-TD w/ 1800 scf air and 10 – 5 bph mist, returns-hvy to med 1/4" coal and shale (95/05) to fines in black to dark gray v

11-04-1999 CO @ 3198'-TD, returns-med to lite 1/8" coal to fines in gray wtr, flow test - 319 mcfd. COOH to DC's, surge 6 times w/ air and mist, 1100 to 1300 psi, returns-coal fines, gas and wtr

11-05-1999 Surge 1 time w/ air and mist to 1350 psi, returns-lite fines, gas and wtr, TIH, tag 3062', CO 3062'-3136', returns-hvy ½" coal at times in black to dark gray wtr, hole would get tight, LD 1 or 2 jts several times, now cleaning out @ 3062'-3086'

11-06-1999 CO 3062'-3198' w/ 1800-900 scf air and 8-5 bph mist, returns-hvy 14' coal and shale (sometimes 60/40) to fines in brown to gray reducing to lite coal, dry well, flow test

11-07-1999 COOH to DC's, surge natural 4 times, 3 hr SI's-470, 450, 460 and 480 psi, returns-coal fines and black wtr, TIH, 4 hr rig repair, TIH, tag @ 3088', CO 3088'-3167', returns-med 1/8" coal and shale (90/10) to fines in gray wtr

11-08-1999 CO 3167'-3198' w/ 1800-900 scf air and 5-8 bph mist, returns med 1/8" coal and shale (85/15) to fines in gray wtr, dry well, flow test, COOH, RU to run liner

11-09-1999 Run 6 jts 5/1/2" liner, could not get down w/ liner, COOH, all slips and bow springs broken off liner hanger, WO liner hanger, TIwash liner 60' to bottom, hang liner and release liner, LDDP, TIH w/ tubing, mill perforation plugs, land tubing, ND BOP, NU WH, pump off expendable check, RD, rig released @ 0600 hrs-11/09/99

ROSA UNIT #232 FRT

ROSA UNIT #232	10/31/98 0:00	8067
ROSA UNIT #232	11/30/98 0:00	14990
ROSA UNIT #232	12/31/98 0:00	11299
ROSA UNIT #232	1/31/99 0:00	7133
ROSA UNIT #232	2/28/99 0:00	7831
ROSA UNIT #232	3/31/99 0:00	12976
ROSA UNIT #232	4/30/99 0:00	12214
ROSA UNIT #232	5/31/99 0:00	13407
ROSA UNIT #232	6/30/99 0:00	11159
ROSA UNIT #232	7/31/99 0:00	9264
ROSA UNIT #232	8/31/99 0:00	5421
ROSA UNIT #232	9/30/99 0:00	8741
ROSA UNIT #232	10/31/99 0:00	2922
ROSA UNIT #232	11/30/99 0:00	4993
ROSA UNIT #232	12/31/99 0:00	13072
ROSA UNIT #232	1/31/00 0:00	16210
ROSA UNIT #232	2/29/00 0:00	14418
ROSA UNIT #232	3/31/00 0:00	15250
ROSA UNIT #232	4/30/00 0:00	15325