UNITED STAT	ES			La companya da
DEPARTMENT OF INTERIOR		5. Lease Designation and Serial No.		
BUREAU OF LAND MANAGEMENT		SF-078774		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to		6. If Indian, Allottee or	Tribe Name.	
deepen or plug back to a different reservoir. Use Form 3160-3 for such proposals.)		7. If Unit or CA, Agreement Designation.		
1. Oil well [] Gas Well [X] Other []		ROSA UNIT		
Gas Well		8. Well Name and No.		
2. Name of Operator		ROSA UNIT #315		
Evergreen Operating Corporation		9. API Well No.		
3. Address & Telephone No. (505) 334-2555		30-039-25219		
c/o A. R. Kendrick, Box 516, Aztec, NM 87410				
4. Location of Well (Footage & S.T.R.)		Basin-Fruitland Coal Gas Pool		
2548' FSL 2066' FWL		11. County or Parish, State		
K - 30 - T 31			riba, New M	exico
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF	NOTICE, REPORT, OR		
[•] Notice of Intent	[] Abandonment		[] Change Plar	
	[] Recompletion		[] New Constr	
[] Subsequent Report	[] Plugging Back		[] Non-Routin	=
	[] Casing Repair		[•] Water Shut	
[] Final Abandonment Notice [] Altering Casing			[] Conversion	•
	[•] OtherSuspens	ion of Operations	[] Dispose Wa	ter
Completion: See attachment	n E G	2 6 1993 ON. DIV.	070 FARMI	RECE BI 93 MAY 20
	OIL C	oist. 3	070 FARMINGTON, NM	PHI2: 04
	THIS APPROVAL EXP		93	
NOTE: This form is submitted in lieu		5.		
14. I hereby certify that the foregoi	· /	A •	- .	May 10 1007
Signed WK Jeuguice	KcTitle	Agent	Date	May 19, 1993
Approved by	Title	•	- Hoate t	HOVED
Conditions of approval, if any:		1993 ; 1993		

NMOCD

Lease No. SF-078774 Evergreen Operating Corporation Rosa Unit #315 2548' FSL 2066' FWL, K-30-31N-4W

T.D. = 3500' K.B.; Production Casing set and cemented @ 3499' K.B.

TOP OF CEMENT @ ±2900' K.B.

COMPLETION: Intend to pressure test the casing, then stimulate the well as shown on the approved APD.

AFTER STIMULATION:

RUN cement bond log to determine cement top from first cement job.

SET bridge plug near top of cement. PERFORATE four squeeze holes 100'± above cement top.

SET cement retainer 300'-400' above retainer.

MIX AND PUMP Halliburton Lite cement calculated to fill annulus and follow with 100 Sx Class B neat cement and displace to cement retainer. Cement volume will be determined from wireline log volume analysis.

IF CEMENT DOES NOT CIRCULATE will run cement bond log to determine cement top.

Operations were suspended for the winter due to U.S. Forest Service Regulations.

Construction of the gas gathering system was also suspended for the winter by the Service.

Due to the classification of the Mexican Spotted Owl as an endangered species, construction of portions of the gas gathering system has been delayed, beyond our control, pending ecien by the Fish and Wildlife Service.

Therefore; we hereby request approval for further suspension of field operations until a chance for a return-on-investment possibility can be reasonably anticipated, or until the last day of 1993 operations authorized by the U.S. Forest Service, being **October 31, 1993**.