



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**  
Governor  
**Betty Rivera**  
Cabinet Secretary

**Lori Wrotenbery**  
Director  
**Oil Conservation Division**

September 6, 2002

Mr. Vern Hansen  
Williams Production Co. LLC  
1 Williams Center  
PO Box 3102, MS 25-1  
Tulsa, OK 74172

Dear Mr. Hansen:

After our conversation on September 3<sup>rd</sup> concerning non-standard proration units defined by NM OCD order R-2046, I checked completions of the Basin Dakota Pool in the sections forming the east side of T31N, R6W. There are five wells in those sections that are out of compliance with R-2046 (see list below).

Rosa Unit #149B in E, Sec 12, T31N, R6W, API# 30-039-26599  
" " # 30B in N, Sec 12, T31N, R6W, API# 30-039-26601  
" " # 30 in O, Sec 12, T31N, R6W, API# 30-039-25570  
" " #125E in B, Sec 13, T31N, R6W, API# 30-039-25526  
" " #116 in A, Sec 24, T31N, R6W, API# 30-039-23484

These wells must be brought into compliance with R-2046, or a hearing must be held to modify the R-2046 gas proration units involved.

Thank you for your attention on this matter.

Sincerely,

Steven N. Hayden  
Geologist, District III  
[shayden@state.nm.us](mailto:shayden@state.nm.us)

SNH/mk

cc: Mike Turnbaugh, Williams Production Co. LLC  
John Thompson, Walsh Engineering  
Well files