## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checkin	ng Below
Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner
Notice of Intention to Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)
Notice of Intention to Gun Perforate	Notice of Intention (Other)	Notice of Intention (Other)
OIL CONSERVATION COMMISSIO SANTA FE, NEW MEXICO	N Parmington, New Mexi	0 9_16_57 (Date)
Gentlemen:		
		PAN AMERICAN PETROLEUM CORPORATION
(Company or Ope	Liking Gas Unit "A"  Drator)  LEASE	
		MPM, Blanco-Mesaverde Poo
San Jama		,
We propose to workover	the above well as follows:	
<ol> <li>Hove in and rig up</li> <li>Clean out hole with</li> <li>Run 5" liner to total</li> </ol>	workover rig. gas to total depth, or whipst	tock hole, if necessary.
<ol> <li>Hove in and rig up</li> <li>Clean out hole with</li> <li>Run 5" liner to total</li> </ol>	workover rig.  gas to total depth, or whipsel al depth & cement. d perforate selected sones.	toek hole, if necessary.
1. Hove in and rig up to 2. Clean out hole with 3. Run 5" liner to total 4. Drill out coment and 5. Stimulate with sand-	workover rig.  gas to total depth, or whipst al depth & cement. d perforate selected soneswater frac.	OIL CON. GST. 38
<ol> <li>Hove in and rig up</li> <li>Clean out hole with</li> <li>Run 5" liner to total</li> <li>Drill out cement and</li> <li>Stimulate with sand</li> </ol>	workover rig.  gas to total depth, or whipst al depth & cement. d perforate selected soneswater frac.	ERICAN PETROLEUM COEPORATION Company or Operator ORIGINAL SIGNED BY
1. Move in and rig up to 2. Clean out hole with 3. Run 5" liner to total 4. Drill out coment and 5. Stimulate with sand-Approved	gas to total depth, or whipst al depth & cement. i perforate selected sones.  water frac.  19 PAN AME  By	CRICAN PETROLEUM CORPORATION Company or Operator ORIGINAL SIGNED BY  D. I. SCOTT
2. Clean out hole with 3. Run 5" liner to tota 4. Drill out coment and 5. Stimulate with sand- Approved	gas to total depth, or whipst al depth & cement. i perforate selected sones.  water frac.  By	ERICAN PETROLEUM CORPORATION Company or Operator ORIGINAL SIGNED BY D. J. SCOTT

	OIL CONSERVATION COMMISSION
	AZTEC DISTEICT OFFICE
	No. Opples Parelled 4
	Photograph Chi
	15.
	781412
	to and the
·	State Land Office
	U. S. G. S.
in the state of the graph of of	Transporter
	File
	The second secon

.

• • •