

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Designation and Serial No. SF-07824-A	
2. Name of Operator Amoco Production Company		6. If Indian, Allottee or Tribe Name	
Attention: Mike Curry		7. If Unit or CA, Agreement Designation	
3. Address and Telephone No. P.O. Box 800, Denver, Colorado 80201		8. Well Name and No. Bassett #1	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 990'FSL 990'FWL Sec. 33 T 30N R 10W		9. API Well No. 3004508936	
		10. Field and Pool, or Exploratory Area AZTEC FRT. Sanel	
		11. County or Parish, State San Juan New Mexico	

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent <input type="checkbox"/> Subsequent Report <input type="checkbox"/> Final Abandonment Notice	<input checked="" type="checkbox"/> Abandonment <input type="checkbox"/> Recompletion <input type="checkbox"/> Plugging Back <input type="checkbox"/> Casing Repair <input type="checkbox"/> Altering Casing <input type="checkbox"/> Other _____ <input type="checkbox"/> Change of Plans <input type="checkbox"/> New Construction <input type="checkbox"/> Non-Routine Fracturing <input type="checkbox"/> Water Shut-Off <input type="checkbox"/> Conversion to Injection <input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The captioned well will be P&A'd per the attached procedures.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

070 EXAMINATION, NM

54 FEB 10 PM 2:36

RECEIVED
BLM

14. I hereby certify that the foregoing is true and correct

Signed Mike Curry Title Business Analyst Date 02-08-1994
(This space for Federal or State office use)

Approved by _____ Title _____
Conditions of approval, if any:

APPROVED

FEB 15 1994

DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

Bassett Federal #1
PXA Procedures

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOPE.
3. POOH with 1' tbg and lay down. RIH with 2 3/8" tbg and cement retainer, set retainer at 2175'. Test casing integrity to 500#. Squeeze perfs at 2224' to 2250' with 51.03 cuft cement. Pull out of retainer and spot cement plug to 2000'. (32.681 cuft) Fill hole with 9ppg mud to 1162'.
4. RIH with perf gun and shoot squeezes holes at 1162'. RIH with cement retainer attempt to circulate to surface. If unable to circulate make sure you have 100' of cement inside and outside csg to cover Ojo Alamo. (53.33 est to top)
6. Pull up hole and shoot squeeze holes at 150'. Circulate to surface and displace cement inside csg to surface. (80 cuft cement)
7. NDBOPE. Cut off casing and wellhead. Install PXA marker according to BLM and State requirements.
8. Turn over to John Schwartz for reclamation.
9. Rehabilitate location according to BLM or State requirements.

BASSETT 001
Location - 33M-30N-10W
SINGLE FS
Orig. Completion - 5/52
LAST FILE UPDATE - 1/94 BY CSW

BOT OF 8.625 IN OD CSA 100
24 LB/FT J-55 CASING, W/50 SKS
CTR TO SURFACE

OJ AT 1162
KL AT 1271

ET AT 2075

ft--1SPF PERF 2224-2250]

BOT OF 1 IN OD TBG AT 2210

PC AT 2433

PBTD AT 2400 FT.

cibp AT 2400
BOT OF 5.5 IN OD CSA 2426
H-40 CASING, W/125 SKS
TOC-1700

TOTAL DEPTH 2525 FT.

orig pc open hole (2426-2525)
completion. pc abnd 1975;
recomp to pc

FILENAME:
04508936

IN REPLY REFER TO:
(07337)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
1235 La Plata Highway
Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 1 Bassett Federal

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.

3. The following modifications to your plugging program are to be made (when applicable):

1.) Perforate @ 1321'; and at a minimum, place a cement plug from 1321' to 1112' inside & outside the casing plus 100% excess in the annulus and 50 linear feet excess inside the casing. (Oso Alamo 1271' to 1162')

Office Hours: 7:45 a.m. to 4:30 p.m.