

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Julander	
9. Well No. 1	
10. Field and Pool, or Wildcat Fulcher Basin	
12. County San Juan	

**SUNDY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER-

Name of Operator  
Flag-Redfern Oil Co.

Address of Operator  
P O Box 208, Farmington, NM 87401

Location of Well  
UNIT LETTER L FEET FROM THE 1890 South LINE AND 800 FEET FROM  
West 34 TOWNSHIP 30 North RANGE 12 West NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
5736 GL


Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
ILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug and abandon as follows:

1. Clean out to TD @ 1916'. Set bottom plug 1916' - 1515'.
2. Attempt to pull 7" casing.
3. Set 100' plug at casing stub.
4. Set 100' plug separating the Fruitland and Farmington Formations @ 700' - 800' in + out of casing.
5. Set 200' plug across Ojo Alamo formation @ 436' - 636' in + out of casing.
6. Set 20 sack plug at the surface.
7. Set dry hole monument.
8. Clean and restore location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Sherman E. Dugan TITLE Agent DATE 5-5-82

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT #3

MAY 6 1982

PROVED BY TITLE DATE