

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Southland Royalty Company 3. Address of Operator P.O. Drawer 570, Farmington, New Mexico 87499 4. Location of Well UNIT LETTER G 1970 FEET FROM THE N LINE AND 1650 FEET FROM THE E LINE, SECTION 32 TOWNSHIP 30N RANGE 12W NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 5423' GL | 7. Unit Agreement Name 8. Farm or Lease Name Sammons 9. Well No. #1 10. Field and Pool, or Wildcat Fulcher Kutz PC 12. County San Juan |
|--|--|

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUS AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUS AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-10-83 Pull and inspect 1" tubing. Ran 1" tubing and spotted 17 sacks cement from 1605' to 1450'.

1-11-83 Spotted 39 sacks cement from 1320' to 1100'. Determined free point and shot off casing at 1001'. Spotted 21 sacks cement plug at 1000' down casing. Pull casing, spotted 105 sacks cement from 80' to surface. Cut off casing and installed dry hole marker.

RECEIVED
OCT 17 1983

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gholson TITLE Engineer DATE January 17, 1983

Original Signed CHARLES GHOLSON

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: