

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved,  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

14-08-0001-8200

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo-Ute Mountain

7. UNIT AGREEMENT NAME

Horseshoe Gallup Unit

8. FARM OR LEASE NAME

Horseshoe Gallup

9. WELL NO.

141

10. FIELD AND POOL, OR WILDCAT

Horseshoe Gallup

11. SEC., T., R., M., OR BLM. AND  
SURVEY OR AREA

Sec. E-30N-16W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use APPLICATION FOR PERMIT—" for such proposals.)1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Water Injection

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

1340 Lincoln Street, Suite 501, Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

Unit P, 860' FSL &amp; 660' FEL, Section 5

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5278' GR

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other) Shut In, Extension Request


(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was shut in during June 1970 because the production supported by the well made it uneconomical to operate.

This well is in a large Unit which is now under waterflood operations. Future plans are to conduct waterflood and tertiary recovery studies. These studies may result in a revised waterflood plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.

U.S.G.S. approval to shut in well June 27, 1970.

TEMPERATURE  
EXPIRES  
JUN 1 1971

Two copies sent to New Mexico Oil Conservation Commission

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 6/4/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

\*See Instructions on Reverse Side