

DISTRICT I
P.O. Box 1988, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Aramis, NM 88238

DISTRICT III
1000 Rio Bonito Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-09921
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name RHODA ABRAMS
8. Well No. 2
9. Pool name or Willcox BASIN DAKOTA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator CONOCO INC.	
3. Address of Operator 10 Desta Drive STE 100W, Midland, TX 79705	
4. Well Location Unit Letter H 1795 Feet From The NORTH Line and 960 Feet From The EAST Line Section 5 Township 30 N Range 11 W NE/4 SAN JUAN County M. Elevation (Show whether D.P., R.R., RT., CR., etc.) 5765'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPER. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-4-94 MIRU. POOH W/ TBG. PACKER WOULD NOT RELEASE. SHOOT OFF TBG @ 6005'.
PLUG #1 & #2. FROM 6005' TO 5810' PUMP 30 SX CLASS B CMT. POOH. GIH TAG CMT @ 5662'. PUH
TO 3875'. ESTABLISH CIRC. PLUG #3 FROM 3875 TO 3717 PUMP 12 SX CLASS B CMT. POOH. GIH TAG
CMT @ 3710'. PLUG 4 FROM 2298' TO 1543' W/ 12 SX CLASS B CMT. GIH & PERF 4 HOLES @ 1672'
POOH. GIH W/ 4 1/2" CMT RETAINER SET @ 1609'. PLUG #5 SQUEEZE 46 SX BELOW RETAINER AND
SPOT 5 SX ABOVE RETAINER TO 1543'. POOH. PERF 4 HOLES @ 902'. GIH W/ 4 1/2" CMT RETAINER
SET @ 853'. PLUG 6 SQUEEZE 90 SX BELOW RETAINER AND SPOT 19 SX ABOVE RETAINER TO 603'
PERF 2 HOLES @ 344'. ESTABLISH CIRC OUT BRADENHEAD. PLUG #7 FROM 344' TO SURFACE W/ 111
SX CLASS B CEMENT. CIRCULATE GOOD CMT TO SURFACE. DIG OUT WELLHEAD AND CUT OFF.
INSTALL P&A MARKER W. 20 SX CLASS B CMT.
1-10-94 RDMO. CHARLIE GHOLSON W/ OCD WAS ON LOCATION.

RECEIVED

JAN 24 1994

OIL CON. DIV

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Krathly TITLE SR REGULATORY SPEC. DATE 1-19-94
TYPE OR PRINT NAME BILL R. KRATHLY TELEPHONE NO. 915-686-5424

(This space for State Use) Charles Gholson DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JUN 24 1994
APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY: