



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Santa Fe,Lease No. N.M. 012509

Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL..... <input checked="" type="checkbox"/>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 20, 1960

Well No. 1 is located 370 ft. from N line and 1030 ft. from W line of sec. 4

NE 1/4 (1/4 Sec. and Sec. No.) T10N (Twp.) R14E (Range) N47W (Meridian)  
undesignated (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5296 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

## Plan to abandon well:

1. Pull slotted liner 5025-9123
2. Spot 15 cu. cement T.D. to 5000.
3. Spot 30 cu. cement across casing stab.
4. Recover 3/4 casing from free point.
5. Spot 30 cu. cement from 1150 to 950
6. Spot 10 cu. cement from 30 to surface.
7. Install dry hole marker.
8. Clean up location.

RECEIVED  
JUN 20 1960

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Albert C. Bruce  
Address 209 Center Bldg.  
Midland, Texas

By J. H. Shoup  
Title Consulting Engineer