



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178 Fax (505) 334-6170

GARY E. JOHNSON
GOVERNOR

JENNIFER A. SALISBURY
CABINET SECRETARY

August 25, 1997

Mike Turnbaugh
Williams Production Co
3102 37- 4
1 Wms Ctr
Tulsa Ok 74101

RE: Rosa #35X, K-05-31N-06W, 30-045-10996

Dear Mike:

I have enclosed a copy of the 1997 Bradenhead Test which shows 410 psi on the BH. The pressure bleeds down quickly which indicates it could be a seal problem. Although the casing doesn't show to be in communication with the BH the excess pressure could cause problems. You are hereby directed to repair the well and retest the BH.

Sincerely:

Johnny Robinson
Deputy O&G Inspector

JR/sh

cc: Well File
BH File
Jim West (Williams Prod Co PO Box 215 Bloomfield)