

RIJAN OIL COMPANY, INC.

Korber Building

ALBUQUERQUE, NEW MEXICO 87101

September 29, 1967

Mr. P. T. McGrath
District Engineer
U. S. Geological Survey
P. O. Box 959
Farmington, New Mexico

RECEIVED

OCT 2 1967


U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

Dear Mr. McGrath:

Please find enclosed our well completion report, Form 9-330 for the No. 1 Rijan well. Prior to drilling this well we found we were unable to reach the location due to marshy ground caused by water seepage. As a result we constructed a pad of gravel and rock for the rig to sit on while drilling. While cleaning up the location after drilling we removed the gravel pad around the location but did not remove the 150' feet of gravel road into the location which is in part sitting on gravel itself. Mr. Daniel J. Yazzie, surface owner, had asked us to do this and we believe we have done this to his satisfaction. We have also paid Mr. Yazzie for access to the location and for use of the gravel.

Schlumberger has previously mailed copies of the electric log to you and to the State office. If those copies did not reach you please let me know and I will mail you some additional copies.

Very truly yours,


Val R. Reese

VRR:lmr
encl: as noted