

RIJAN OIL COMPANY, INC.

Korber Building

ALBUQUERQUE, NEW MEXICO 87101


March 28, 1968

Mr. Emery C. Arnold
Supervisor, Oil & Gas Commission
1000 Rio Brazos Road
Aztec, New Mexico.

Dear Sir:

In compliance with the Oil Conservation Commission Rule No. 111, straight hole deviation tests were made on our No. 5 Rijan well while drilling. The No. 5 Rijan well is located 2250' FWL and 210' FWL in Sec. 31 of Twp. 30 Nor. Range 16 W, San Juan County, New Mexico. One test was taken February 22, 1968 at 400' while drilling and was off 1/2 degree from vertical. A second test was made at 900' and was off 3/4 of a degree from vertical, on March 23, 1968. Hole depth is 910 feet.

Yours truly,



Val R. Reese, Geologist
Rijan Oil Company

Subscribed and sworn to before me this 29 day of

March 1968.

Olga W. Hagerman
Notary Public

My commission expires May 10, 1970.

