Form 3160-5 (June 1990)

Conditions of approval, if any:

representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals		Expires: Marc	Expires: March 31, 1993	
		5. Lease Designation and Serial No. SF-080244 6. If Indian, Allottee or Tribe Name		
		7. If Unit or CA, Agreement De	esignation	
1. Type of Well Oil Gas Wall Other		B. Well Name and No.		
2. Name of Operator	Attention:	Riddle H	8X	
Amoco Production Company 3. Address and Telephone No.	Patty Haefele	300452)1175	
P.O. Box 800, Denver, Colorado 80201	(303) 830-4988	10. Field and Pool, or Explorate		
			Blanco Pictured Cliffs	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State		
1820' FSL 1095'FEL Se	c. 7 T 30N R 9W	San Juan	New Mexico	
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER	DATA	
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly state all pertine subsurface locations and measured and true vertical depths for all resources.)	Recompliant details, and give pertinent dates, including estimated date of star		irectionally drilled, give	
	COR COM. EN DIST. 8		The state of the s	
14. I hereby certify that the foregoing is true and correct Signed	Title Staff Ass		06-23-1995 ENDED	
A	Title	AS,AM	FINDED	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious

SJOET Well Work Procedure

Riddle H 8X

Version:

#1

Date:

June 23, 1995

Budget:

DRA **PXA**

Objectives:

Repair Type:

To PXA the entire well

Reason: Unable to produce in paying quanities.

Pertinent Information:

Location:

1820' FSL 1095' FEL Sec 7 T 30N R 9W

Horizon:

PC

API #:

3004521175

County: State: Lease:

New Mexico BLM SF-080244 Engr: Phone: Wyett/DeHerrera H--(303)-830-5578

Well Flac:

979220

San Juan

W-(303)-368-7795

Economic Information:

APC WI:

.25

Estimated Cost:

\$18,000.00

Formation Tops: (Estimated formation tops)

Nacimento:

515 est

Oio Alamo:

1872

Menefee:

Kirtland Shale:

2049

Point Lookout: Mancos Shale:

Fruitland: Pictured Cliffs: 3228 to PBTD

Gallup: 2840 Graneros:

Lewis Shale: Cliff House:

Dakota: Morrison:

Bradenhead Test Information:

7/18/87 Tubing:

290

Casing:

BH: 0

Test Date:

90 CSG

INT CSG Time BH 90 5 min 90 10 min 90 15 min

Comments:

Riddle H 8X Orig. Comp. 1/73 TD = 3325', PBTD = 3278' Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water.
- 3. POOH with 2 3/8" tbg. NDWH. NUBOP. RIH with tbg and cement retainer. Set retainer at 3175'. Test casing integrity to 500#.. Squeeze perfs at 3234' to 3260' with cuft of cement. Pull out of retainer and spot cement plug to 2775 with 28 cuft cement.
- 4. RIH with perf gun and shoot squeeze holes at 565. RIH with cement retainer and set 50' above squeezes holes and attempt to circulate to surface with 234 cuft cement. Pull out of retainer and fill hole to surface with 46 cuft cement.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 6. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 7. Turn over to John Schwartz for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

TOTAL DEPTH 3325 FT.

PG--1SPF PERF 1214-1241-3255-3250---

RPFPEES?57831698180 AT 3107

PRT. 8 E 8/FT IN 280 CEASTALS 300 RA Cathodic Protection - ?

17/8 Dise 77/8