

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		51 APR 19 AM 11:42		5. LEASE DESIGNATION AND SERIAL NO. NM-4462	
2. NAME OF OPERATOR Schalk Development Company		OIS FARMINGTON, N.M.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 25825, Albuquerque, NM 87125				7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1190' FSL & 890' FEL				8. FARM OR LEASE NAME Schalk 62	
				9. WELL NO. #1	
				10. FIELD AND POOL, OR WILDCAT Basin Dakota	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33, T-32N, R-5W	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6313' KB		12. COUNTY OR PARISH Rio Arriba	
				13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

On June 22, 1990, we were swabbing this well and sand line parted causing swabb tools to fall down-hole. We tried for 3 days to fish tools from well but were unsuccessful. Our plans at this time are to place a rig on location, pull TBG and retrieve swabb tools, and go back in hole with TBG and swabb well in and place back in production.

RECEIVED

APR 24 1991

OIL CON. DIV./
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

General Manager

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

4/17/91

APR 17 1991

DATE

AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side