District Column	Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources					Re	Form C-10 evised March 25, 19	_	
Bill South First, Amesia, NAM 87310 Database, March Committee Comm	1625 N. French Dr., Hobbs, NM 87240	i25 N. French Dr., Hobbs, NM 87240					WELL API NO.			
STATE FEE	811 South First, Artesia, NM 87210	tesia. NM 8/210								
State Olf & Gas Lease No.							·			
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name:	District IV					6. State Oil & Gas Lease No.				
San Juan 32-5 Unit San Juan 32-5 Unit	SUNDRY NOTIC	ES AND REPORTS C	N WE	LS			Name or Unit Ag	reement Name:	-	
San Juan 32-5 Unit Oil Well Gas Well Dother San Juan 32-5 Unit Oil Well Gas Well Dother San Juan 32-5 Unit Oil Well Gas Well Dother San Juan 32-5 Unit Oil Well Gas Well Dother Section San Juan 32-5 Unit San Juan 32-5 Unit Section Section San Juan 32-5 Unit Section Section San Juan 32-5 Unit Section								,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Offiver Summer of Operator 2. Name of Operator 2. Name of Operator 3. Address of Operator 3. Address of Operator 4. Well Location Unit Letter N : 1070 feet from the South line and 1575 feet from the West line Section 32 Township 32N Range 5M NMPM County Rio Arriba 11. Check Appropriate Box to Indicate Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CRIMENT JUB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud @ 10:00 pm 10/02/01. Drill 12-1/4" hole to 247". Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241". RU Halliburton. Cement with 150 sks Class B poz. 21 CaCI2. 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 an 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. MOC. NU BOP. Test BOP & casing to 600 psi · ok. Title Production Assistant DATE 10/04/01. Type or print name Vicki Donaghey Title Production Assistant DATE 10/04/01. Type or print name Vicki Donaghey Telephone No. 505-325-9732	PROPOSALS.)					San Juan 32-5 Unit				
2. Name of Operator INFREST RESOURCES CORPORATION 3. Address of Operator 2198 Bloomfield Highway. Farminaton, NM 87401. 4. Well Location Unit Letter N : 1070 feet from the South line and 1575 feet from the West line Section 32 Township 32N Range 5M NMPM County Rio Arriba 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6472' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. LATERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON ABANDON CEMENT JOB OTHER: OTHER: Spud 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud @ 10:00 pm 10/02/01. Drill 12:1/4" hole to 247'. Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241'. Rul Halliburton. Cement with 150 sks Class B poz. 24 CaC12. 1/4#/sk flocale (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. Title Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732										
3. Address of Operator 2.198. Bloomfield Highway. Farminaton. NM 87401 Basin Fruitland Coal						8. Well No.				
2198 Bloomfield Highway, Farmington, NM 87401 Basin Fruitland Coal		<u>N</u>								
4. Well Location Unit Letter N : 1070 feet from the South line and 1575 feet from the West line Section 32 Township 32N Range 5W NMPM County Rio Arriba 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6472 GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CHANGE PLUG AND ABANDONMENT COMPLETION CASING TEST AND CEMENT JOB CHANGE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud © 10:00 pm 10/02/01. Drill 12-1/4" hole to 247", Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set © 241". RU Halliburton. Cement with 150 sks Class B poz, 2% Cac12, 1/4#/sk flocele (177 cu.ft.). Plug down © 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WCC. NU BOP. Test BOP & casing to 600 psi - ok. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732						l '				
Section 32 Township 32N Range 5W NMPM County Rio Arriba		######################################				r Dug (III) I	arcrana oour		1	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6472' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENT JOB CHANGE PLANS OTHER: Spud TOTHER: Spu	Unit Letter N :	feet from the	Sou	ıth	line and	1575	feet from the	West line	e	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Spud X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud @ 10:00 pm 10/02/01. Drill 12·1/4" hole to 247'. Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241'. RU Halliburton. Cement with 150 sks Class B poz. 2% CaCl2, 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi · ok. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	Section 32	Township	32N	Range	5W	NMPM	Cour	nty Rio Arriba	1	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CEMENT JOB OTHER: Spud THER: Spud TILLING OPNS. SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud © 10:00 pm 10/02/01. Drill 12·1/4" hole to 247'. Ran 5 jts. 9·5/8" 36# J-55 ST&C casing, set © 241'. RU Halliburton. Cement with 150 sks Class B poz. 2% CaCl2. 1/4#/sk flocele (177 cu.ft.). Plug down © 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi · ok. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732		10. Elevation (Show v			R, RT, GR, et	c.)			8	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDON ABANDON ABANDON ABANDON ABANDON ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT AB	11. Check A	Appropriate Box to I			of Notice.	Report, o	or Other Data	020000200000000000000	<u>9</u> 29	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB TOTHER: Spud T								OF:		
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Spud IX 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud @ 10:00 pm 10/02/01. Drill 12-1/4" hole to 247'. Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241'. RU Halliburton. Cement with 150 sks Class B poz. 2% CaCl2. 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi · ok. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	PERFORM REMEDIAL WORK	PLUG AND ABANDON	۷ 🗆	REMED						
OTHER: CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Spud [X] 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud @ 10:00 pm 10/02/01. Drill 12-1/4" hole to 247'. Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241'. RU Halliburton. Cement with 150 sks Class B poz. 2% CaCl2. 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	TEMPORARILY ABANDON	CHANGE PLANS		соммі	ENCE DRILLI	NG OPNS.				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud @ 10:00 pm 10/02/01. Drill 12-1/4" hole to 247'. Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241'. RU Halliburton. Cement with 150 sks Class B poz. 2% CaCl2. 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	PULL OR ALTER CASING							NO OTHINE IT		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spud @ 10:00 pm 10/02/01. Drill 12-1/4" hole to 247'. Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241'. RU Halliburton. Cement with 150 sks Class B poz, 2* CaCl2, 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	OTHER:			OTHER	: Spud				X	
Spud @ 10:00 pm 10/02/01. Drill 12-1/4" hole to 247'. Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241'. RU Halliburton. Cement with 150 sks Class B poz, 2% CaCl2, 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	12. Describe Proposed or Complete	d Operations (Clearly sta	ate all pe	ertinent d		ve pertinent	dates, including	estimated date		
Spud @ 10:00 pm 10/02/01. Drill 12-1/4" hole to 247'. Ran 5 jts. 9-5/8" 36# J-55 ST&C casing, set @ 241'. RU Halliburton. Cement with 150 sks Class B poz, 2% CaCl2, 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	of starting any proposed work).									
set @ 241'. RU Halliburton. Cement with 150 sks Class B poz, 2% CaCl2, 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	or recompilation.									
set @ 241'. RU Halliburton. Cement with 150 sks Class B poz, 2% CaCl2, 1/4#/sk flocele (177 cu.ft.). Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732										
Plug down @ 10:30 am 10/03/01. Circulated 50 sks cement to surface. RD Halliburton. WOC. NU BOP. Test BOP & casing to 600 psi - ok. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Title Production Assistant Title Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	·				-			•		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732										
SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	Test BOP & casing to 600	psi - ok.						TO S		
SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732							311	237		
SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732							A 0	h = Oh		
SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732							A OFFICE	32 0		
SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732							2 00	2		
SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732							E ay	no 3		
SIGNATURE TITLE Production Assistant DATE 10/04/01 Type or print name Vicki Donaghey Telephone No. 505-325-9732	W					-	TO,		_	
Type or print name Vicki Donaghey Telephone No. 505-325-9732	I hereby certify that the information above	is true and complete to the	best of n	ny knowle	dge and belief.		81.18	1913/1/1		
	SIGNATURE VICKE DO	naglay	TITL	<u>E Produ</u>	<u>iction Assi</u>	stant	DATE _	10/04/01	_	
(This space for SHONED BY CHAPLIE T. PERMIN PETTY OIL & GAS INSPECTOR, DIST. #5	Type or print name Vicki Donaghey	0 0					Telephone No.	505-325-9732	_	
	(This space for State IISAL SIGNED BY	OHARLIE T. PERMIN		DEPTY	OfL & GAS IN	ASPECTOR, 6	NIST. #85			
APPROVED BY TITLE DATE OCT - 5 2001 Conditions of approval, if any:	APPROVED BY		TITI	LE	·		DATE 0	ICT - 5 200	1	