

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency

1-147-113-7453

Allottee

Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 2

1999

Well No. 11 is located 660 ft. from S line and 660 ft. from E line of sec. 9



(1/4 Sec. and Sec. No.)

~~CONFIDENTIAL~~

(Field)

21

(Twp.)

Don Juan

(County or Subdivision)



(Range)

IN THE

(Meridian)

New Member

(State or Territory)

The elevation of the derrick floor above sea level is ~~200~~ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Deepened well from 610' to 1203'

Top of Dakota 1227'

Placed as follows:

25 IN FROM 1109° to 1109°

20 are from 640* to 660*

Connected from 60 ft. to surface -- matted between plugs



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company KING OIL COMPANY

Address 705 Petroleum Club Building

Durango, Colorado

By

Title.

