Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction.

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993


		5. Lesse De	signation and Serial No.				
SUNDRY NOTIC		SF 078097					
Do not use this form for proposal	eservoir.	SF U/809/ 6. If Indian, Allottee or Tribe Name					
	ON FOR PERMIT - " for such proposals	0.11.11.21.1	, , , , , , , , , , , , , , , , , , , ,				
		7. If Unit o	r CA, Agreement Designation				
1. Type of Well Oil S Gee		8. Well Nan	ne and No				
Oil Gas Uther			iton Com B LS 17				
2. Name of Operator	Attention:	9. API Wel					
Amoco Production Company	Julie Acevedo	9. API VVEI	ING.				
3. Address and Telephone No.			3004510144				
P.O. Box 800, Denver, Colorado	80201	10. Field ar	d Pool, or Exploratory Area				
4. Location of Well (Footage, Sec., T., R., M., or Surv			Basin Dakota				
4. Location of Well (Poolage, Sec., 1., 11., 11., 01. Sec.	, See p. 1011	11. County	or Parish, State				
1830' FNL 1470' FEL	Sec. 32 T 31N R 11W						
			San Juan New Mexico				
	E DOVEN TO INDICATE MATURE	E NOTICE BEPORT	OR OTHER DATA				
12. CHECK APPROPRIAT	E BOX(s) TO INDICATE NATURE (		OR OTHER DATA				
TYPE OF SUBMISSION		YPE OF ACTION					
	Abandonment	Change of P	lans				
Notice of Intent	Recompletion	New Comstr	uction				
	Plugging Back	Non-Routine	Fracturing				
Subsequent Report	Casing Repair	Water Shut-	Off				
	Altering Casing	Conversion	to Injection				
Final Abandonment Notice	Other	Dispose Wa					
		(Note: Report results of n Recompletion Report and	sultiple completion on Well Completion or Log form. )				
	se contact Julie Acevedo at 303-830-60 2 1993. ON. DIV. SEE ATTACHEI CONDITIONS OF A	) FOR	SECEIVED  SENT 21, MIO: 42  CO N.C. 21, MIO: 42				
14. I hereby certify that the foregoing is true and correspond to the foregoing to th	Title	Sr Staff Assistant	Date 03-19-1993 PPROVED				
y							
Approved by	Title	C	/ MAR 00 1993				
Conditions of approval, if any:		1 4	TAANACED.				
			TRICT MANAGES				
Title 18 U.S.C. Section 1001, makes it a crime for an	y person knowingly and willfully to make to any department or	agency of the United States any false,	ficticious, or fraudulent statements or				

## PXA Procedures Heaton Com B LS #17

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. TOOH with 2 3/8" tbg. RIH with tbg and retainer. Set retainer at 6725'. Squeeze perfs at 6774' to 7004' with 124 sx class B cement. TOOH laying down tbg.
- 4. Need cement inside pipe (50% excess) at the following areas,
  - a) 6694' to 5878' 50' above and below Gallup
  - b) 4834' to 3950' 50' above and below Mesa Verde
  - c) 2450' to 2302' 50' above and below Pictured Cliffs
  - d) 2402' to 2025' 50' above and below Fruitland Coal
- 5. RIH and perf at 1700'. Circulate water thru casing and out bradenhead. Check valves.
- 6. Attempt to circulate cement to surface. If can not circulate then perf again at 1600' and every 100' until circulation is obtained.
- 7. Rig up to cement, circulate, do not displace.
- 9. NDBOPE. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 10. Turn over to John Schwartz for reclamation.
- 11. Rehabilitate location according to BLM and State requirements.

SSICE 24 AND: 42

#### HEATON COM B LS 017 Location — 32G— 31N—11W Basin Dakota Orig.Completion — 10/61 Last File Update — 1/90



### UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 17 Houten am B LS

#### CONDITIONS OF APPROVAL

١.	Plugging	onei	rations	aut	horized	are	sul	bject	to	the	attac	ched	"General
Reau	irements	for	Permane	ent	Abandon	nent	of	Wells	01	ı Fe	deral	Leas	ses."

- 2. Mark /c//y with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):
- 1) Perforate a 5476 and place a come of play from 5470 to 5878 inside 2 out side the casing plus 1000 excess (Gillip top 5 5926)
- 2.) Bring Fruitherd play back to 1914. (Topol Fruithed 1969)

At a minimum, it seement is not circulated to the Surface from 1266.
1) Perturbe a 1133 and place a coment plan from 1153.

To 914 Plas 100 6 excess inside x outside at the carring (cose Alome 904 to 1103)

Office Hours: 7:45 a.m. to 4:30 p.m.

2) Perferte 2 362 and circulto cement to the