(Romarly 9-331) DEPARTM		INITED STATES ENT OF THE INTERIOR OF LAND MANAGEMENT		BUBMIT IN TRIPLICATI (Other instructions on i verse side)	Expire	Expires August 31, 1985  8. LEASS DESIGNATION AND SERIAL PG. 14-20-604-1951		
		ES AND REF		WELLS o a different reservoir.	Ute Mou	/	OF TRIDE HAME	
I. OIL GAS			<del></del>		1		up Unit	
WELL WELL OTHER Injection Well						8. FARM OR LEASE MANS		
ARCO Oil & Gas Company, Division of Atlantic Richfield Co.					1 /	Hørseshoe Gallup		
3. ADDRESS OF OPERATOR						9. WHILE NO.		
1816 E. Mojave, Farmington, New Mexico 87401  LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface						180		
						ND POOL, OR		
						Horseshoe Gallup		
						11. SEC., T., M., OR BLK. AND SURVEY OR ARMA		
Unit D, 730' FNL & 515' FWL					For 34	Sec. 34, T-31N, R-16W		
PERNIT NO.	J 11L & 313	15. BLEVATIONS (Short	w whether DF. RT. a	R. etc.)	12. COUNTY			
		•	5512' GL		San Jua		NM	
J.	Check Ass	ropusta Roy To I	Indicate Natur	e of Notice, Report, or	Od D-4-			
	NOTICE OF INTENTIO		indicale (Agron					
				#0###	THOTHE THEORY O	<b>7</b> :		
TEST WATER SHUT-		LL OR ALTER CASING		WATER SHCT-OFF		EPAIRING WI	BLL	
FRACTURE TREAT		LTIPLE COMPLETE		FRACTURE TREATMENT	<del>-</del>	LTERING CAS		
SHOOT OR ACIDIZM	1-1	ANDON® Ange Plane		SHOOTING OR ACIDIZING (Other)		Bandorment	·*	
(Other)		ANDE ILENE		(Nors: Report resul Completion or Record	ts of multiple e	mpletion of	n <u>Men</u>	
		ny completed our procedure		operations on Ho as follows:	rseshoe <b>Ga</b>	11up #1	180. The	
<u>Date</u>	Activity							
9/17/87	MIRU PU. SD	ON.						
9/18/87	POH w/tbg. and squeeze surface csg	tom of hole. RIH and perf ed. POH w/th shoe and ci	POH w/tbg 2 holes @ og. Perf 2 irculated c	the hole. Relea . RIH and spot 2 1232'. RIH and holes @ 175'. ement to surface	5 sx plug spot 25 sx Pump 25 s . SDON.	across plug @ x plug	perfs. 3 1232' across	
9/21/87 Approved	Cut off well to the	Thead. Insta	of Late	NOV 0 4 1987 L CON. DIV.	THE MAIN	eres properties and	?	
Well Do the o	re only. L	iability u	inder Surfago	NOV 0 4 1987	<b>y</b> 198	17.		
resto appro	nation is	complete	d aind	DIST. 3	a New James - States	1 <b>(6</b> )		
BIGNED SIGNED	t the foregoing is to			tion Supervisor		9/24/	/87	
(This space for Fed	eral or State office t	Dee)						
APPROVED BY L	. Mark Hollis	<b>T</b> I	ACTIN	G AREA MANAGE	R DATE	NOV 0	3 1987	
APPRO			mocd					
AS AME	NDED	*See Ir	nstructions on F	Reverse Side				

## CONDITIONS OF APPROVAL AND ADDITIONAL REQUIREMENTS

- 1. This Subsequent Report of Abandonment (SRA) is approved to the plugging of the well bore only. Liability under the bond is retained until surface restoration is completed and approved.
- 2. Once the dirt work has been completed, the operator will submit Form 3160-5, Sundry Notice, informing the Bureau of Land Management (BLM) of this operation. This Sundry Notice, or Second Subsequent Report of Abandonment (SSRA) will be an acceptance rather than an approval action. (Instruction Memorandum No. CO-87-417).
- 3. Form 3160-5, Sundry Notice, will be submitted when all restoration is completed. This Sundry Notice, or Final Abandonment Notice (FAN), will be submitted only when the site is ready for inspection by an official of the BLM.
- 4. PHASED RELEASE OF BOND LIABILITY After proper plugging of the leasehold's well(s), and after the site has been stabilized and seeded, a percentage of the bond liability can be released. Operators who wish to request partial liability release of a single lease bond may delay filing Form 3160-5, Second Subsequent Report of Abandonment (SSRA) until after the site has been reseeded. In this case, the Sundry Notice should not only detail work that was done but also request partial bond liability release. (Instruction Memorandum No. CO-87-307).