14-20-604-

5. LEASE

14-08-0001-8200

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOYTEE OR TRIBE NAME
	Navajo - Ote Mtn.
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different	Horseshoe Gallup Unit
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas T	Horseshoe Gallup Unit
well well other Injection	9. WELL NO.
2. NAME OF OPERATOR ARCO Oil and Gas Co., a	175
Div. of Atlantic Richfield Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 707 - 17th Street,	Horseshoe Gallup
P.O. Box 5540, Denver, Colo. 80217	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 26-31N-16W
below.) AT SURFACE: Unit N,660'FSL & 1980'FWL, Sec. 26	
AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO. None
REPORT, OR OTHER DATA	
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5532'
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	U. S. GEOLOGICAL CHOUSE
TEST WATER SHUT-OFF	UIL MIND GAS OPERATIONS
FRACTURE TREAT	COLINED
SHOOT OR ACIDIZE	250 00 1000
PULL OR ALTER CASING	(NOTE: Report) [Again to 3] (Police Completion or zone change on Form 9—330.)
MULTIPLE COMPLETE	
CHANGE ZONES	CDAMP WILLIAM
ABANDON*	GRAND JUNCTION, COLORADO
(Outer) 12 Oct Comerce 1 1 ad	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
ARCO hereby asks permission to set a cement plug above the injection interval(1481-1483') in the subject well. This is in compliance with the requirements as set forth in a memorandum dated September 30, 1981, and a subsequent letter of April 26, 1982, both from the State of New Mexico, Energy and Minerals Department, Oil Conservation	
111771 C100 / C0010 C 1441 Chod \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Attached is the procedure for setting the	Acement plug.
SEP 3 0 19	82 REGEIVED
V Juliu SUN. CC	λ. / 'II (100)
DIST. 3	SEP 1 6 1982
Subsurface Safety Valve: Manu. and Type	MINERAIS MANAGEMENT SE. Ft.
18. I hereby certify that the foregoing is true and correct	·
SIGNED SIC ROSE TITLE DIST. Prod.S	Supt.oate August 31, 1982
(This space for Federal or State office use)	
APPROVED BY Original Signed - Scott L. Ellisite JOHN L. PR	RICE: Prisor DATE SEP 2 4 1982
CONDITIONS OF APPROVAL IF ANY:	NISOT DATE SEP 2 4 1982
The state of the s	
ATTACHED	

HORSESHOE GALLUP UNIT INJECTION WELLS

PLUGGING PROCEDURE

- 1. MIRU.
- 2. Release packer and pull tubing and packer out of hole.
- 3. RIH with tubing open-ended to 40' above the top perforation and pump sufficient cement to set a 100' plug inside the casing (Using light-weight cement).
- 4. POH, RD, and move off.





STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

BRUCE KING SOVERNOR ARRY KEHOE

April 26, 1982

POST OFFICE BOX 2088 STATE LAND OFFICE BUILDING SANTA FE, NEW MEXICO 87501 (505) 827-2434

RECEIVED

APR 30 1982

ENGINEERING

Arco Oil & Gas Company P.O. Box 5540 Denver, Colorado 80217

ATTENTION: J. G. Bradshaw

RE: Exception to Rule 705-A for Injection Wells in the Horseshoe Gallup Unit, Federal Lease No. 14-08-0001-8200, San Juan County,

New Mexico.

Dear Sir:

Pursuant to your letter of February 18, 1982, requesting exception to Rule 705-A for fifty-seven (57) wells as listed on Table I, the Oil Conservation Division hereby denies both of your requests. You are hereby requested to take prompt action as outlined in the September 30, 1981, Memorandum. (Copy enclosed).

The Oil Conservation Division will not grant an exception to Rule 705-A if a well will not be placed in service within 6 months of the request. For future reference, supportive data for exception to Rule 705-A should include:

- 1. Proof of mechanical integrity, such as bradenhead tests, tracer logs, or other supportive tests or data.
- 2. All related OCD Division Order Numbers or Case Hearing Numbers.
- 3. A schematic of the present injection well including cement tops and quantities thereof.
- 4. Date each well was shut-in.

If you have any questions regarding this matter, please do not hesitate to contact me at (505) 827-2533.

Sincerely,

JOE D. RAMEY

Division Director

TABLE I

Horeshoe Gallup Unit Federal Lease No. 14-08-001-8200 San Juan County, New Mexico.

List of Wells

- 1. No. 26 B
- 2. No. 29 B
- 3. No. 103 A
- 4. No. 105 A
- 5. No. 113 A
- 6. No. 126 C
- 7. No. 130 C
- 8. No. 132 C
- 9. No. 135 C
- 10. No. 137 C
- 11. No. 139 C
- 12. No. 141 C
- 13. No. 143 D
- 14. No. 145 D
- 15. No. 148 D
- 16. No. 150 D
- 17. No. 152 D
- 18. No. 154 D
- 19. No. 156 D
- 20. No. 160.

- 21. No. 215 D
- 22. No. 162 D
- 23. No. 164 D
- 24. No. 169
- 25. No. 171
- 26. No. 173
- 27. No. 175
- 38. No. 180
- 29. No. 182 D
- 30. No. 184 \mathcal{D}
- 31. No. 186
- 32. No. 192
- 33. No. 194 D
- 34. No. 196 D
- 35. No. 201
- 36. No. 203
- 37. No. 205 D
- 38. No. 207 D
- 39. No. 213 📮
- 40. No. 217 D

- 41. No. 223 D
- 42. No. 225 D
- 43. No. 227 D
- 44. No. 229 D
- 45. No. 238 D
- 46. No. 240 D
- 47. No. 248 D
- 48. No. 250 D
- 49. No. 259 D
- 50. No. 261 C
- 51. No. 263 C
- 52. No. 269 C
- 53. No. 274 C
- 54. No. 275 C
- 55. No. 73 A
- ...

56. No. 199

No. 211

SEP 3 0 1982 OIL COM. COM. DIST. 3



ENERGY AND IVIINERALS DEPARTIVIENT OIL CONSERVATION DIVISION

POST OFFICE BCX 20 STATE LAND OFFICE BL SANTA FE NEW MEXICO: (505) 827-2404

BRUCE KING SOVERNOR LARRY KEHOE SECRETARY

MEMORANDUM

TO:

ALL NEW MEXICO INJECTION WELL OPERATORS

FROM:

JOE D. RAMEY, DIRECTOR

SUBJECT:

TEMPORARY ABANDONMENT OF INJECTION WELLS

Division Rule 705A provides in part that "no injection well may be temporarily abandoned for more than six months unless the injection interval has been isolated by use of cement or a bridge plug." The Division Director may delay the cement or bridge plug requirement upon a request by the operator and a showing that such well is mechanically sound, that there is a continuing need for the well, and that the well constitutes no threat to underground sources of drinking water.

Division survey programs have found several hundred injection wells which have not been used for at least six months and which do not have the requisite plugs. Based upon these surveys the Division will be moving to enforce Rule 705A in the near future.

Operators should review the status of their injection wells and within the next six months take one of the following actions relative to injection wells which have been shut in for six months or longer:

- (1) Return the well to active operation.
- (2) Plug and abandon the well or place a <u>cement</u> or bridge plug above the injection interval.
- (3) File a workover or plugging plan and schedule with the appropriate Division district office.
- (4) File a request for exception to Rule 705A with the Division Director in Santa Fe.

September 30, 1981 fd/

CONDITIONS FOR APPROVAL

- 1. Plug to be tagged or pressure tested to 1000 psi.
- 2. Casing at the surface shall be secured with a valve or cap.
- 3. Approval effective for one year only.

