

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

3004510737

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

Ground Bed Abandonment

2. Name of Operator

Amoco Production Company

Attention:

Patty Haefeale

8. Well No.

1

3. Address of Operator

P.O. Box 800

Denver

Colorado

80201

(303) 830-4988

9. Pool name or Wildcat

Blanco Mesaverde

4. Well Location

Unit Letter H : 1910 Feet From The North Line and 990 Feet From The East Line

Section

18

Township

31N

Range

10W

NMPM

San Juan

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

5766' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Ground Bed Abandonment ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company intends to plug and abandon the cathodic protection well associated with the above well per the attached procedure.

RECEIVED
JUN 1 9 1995
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Patty Haefeale

TITLE

Staff Assistant

DATE

06-15-1995

TYPE OR PRINT NAME

Patty Haefeale

TELEPHONE NO. (303) 830-4988

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH

TITLE

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

JUN 2 0 1995

CONDITIONS OF APPROVAL, IF ANY:

Ground Bed Abandonment Procedures

Well Name: McCoy Gas Com A #1

Location: 18H-31N-10W

1. Weld 6" dia. spool with diverter line to pit
2. MIRU
3. Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free. Wash hole to 300' (TD).
4. Pump adequate cement to partially fill hole (approx. 95 sx). Pull out work string.
5. Top off hole with cement from top of first cement plug. Set flexible pipeline marker as PxA marker.
6. RDMO

Ground Bed Specifications

TD:

Hole Dia.: 7"

Casing Dia.: 7"

Casing Length: 85'