

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
MAR - 1 1996

WELL API NO. 3004510737
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name McCoy Gas Com "A"
8. Well No. 1
9. Pool name or Wildcat Blanco Mesaverde
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5766' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Amoco Production Company
Attention: Patty Haefe
3. Address of Operator P.O. Box 800 Denver Colorado 80201 (303) 830-4988
4. Well Location Unit Letter H : 1910 Feet From The North Line and 990 Feet From The East Line Section 18 Township 31N Range 10W NMPM San Juan County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5766' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Ground Bed Abandonment ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company has performed a ground bed abandonment associated with the above well.

MIRUSU 11/29/95. TIH with 4" cone bit and drill out wire and vent pipe to 35', wire off bit to 95'. TIH with cone bit to 95' - unable to make hole. TIH with junk mill, drill to 108' end of casing. TOH. Drilled with cone bit to 120'. Weld nipple on top of collar. Drill with cone bit to 150', hit anode. Drilled out to 158' with air hammer. Drill with cone bit to 160' - unable to make hole. TIH with mill. TOH with ball of wire to 80' work pipe out. TIH with cone bit to 120' - having problems with casing, casing parted. Contacted NMOCD - received permission to plug from 120'. Drill with cone bit on rocks at 85' to 120' - unable to make any hole. Rig up coil tubing. RIH and plug from 120' to surface with 30 sx cement and cap off casing. Ground bed plugged and abandoned. RDMOSU 12/5/95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patty Haefe TITLE Staff Assistant DATE 02-29-1996
TYPE OR PRINT NAME Patty Haefe TELEPHONE NO. (303) 830-4988

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH

DATE MAR - 4 1996

CONDITIONS OF APPROVAL, IF ANY: