


COPY FOR  
STATE OF NEW MEXICO  
**OIL CONSERVATION  
COMMISSION**  
SUBMIT IN TRIPLICATE TO  
DISTRICT OFFICE

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

Land Office Santa Fe

Lease No. 078115

Unit Grenier #5



**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... March 19 ....., 1952

Well No. 5 Grenier is located 990 ft. from N line and 1650 ft. from W line of sec. 13

NE<sup>1</sup> NW<sup>1</sup> Sec. 13..... T-31N..... R-12W..... N.M.P.M.  
(<sup>1</sup>/<sub>4</sub> Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Blanco-La Plata..... San Juan County..... New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6202 ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

Rotary total depth 4345. Cemented 4350' 7" w/<sup>200</sup>/<sub>150</sub> sacks.  
Cable tools moved on and drilled cement plug, March 16,  
1952. Swabbed hole dry. Tested with 500# pressure for  
2 hours, hole dry and pipe O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AZTEC OIL AND GAS COMPANY

Address 1104 Burt Building

Dallas, Texas

By H. C. Murphy  
Title Drilling Superintendent