

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other WIW

2. Name of Operator
BK Petroleum, Inc.

3. Address and Telephone No.
P.O. Box 826, Farmington, NM 87499-0826 505-326-3139

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

360' FNL, 855' FEL, Sec. 18, T31N, R16W

5. Lease Designation and Serial No.

14-20-6000-3531

6. If Indian, Allottee or Tribe Name

Navajo - Ute Mtn.

7. If Unit or CA, Agreement Designation

Many Rocks Gallup Proj.

8. Well Name and No.

Many Rocks Gallup

9. API Well No.

16

10. Field and Pool, or Exploratory Area

Many Rocks Gallup

11. County or Parish, State

San Juan County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Return well to production

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recomplet on Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Per your letter request dated May 3, 1993 the following has been done to return this former water injection well to production: (7/23/93). Rig up well service unit. Release Model A Baker injection packer. Trip out of hole. Go back in hole with scraper and circulate hole clean. Trip out. Go in hole with production tubing. Swab well into workover tank to ascertain commercial production. Well swabs at the rate of 3 bopd and 12 bwpd. Run 2' x 1-1/2" x 8' RWAC inset pump and 5/8" rods. Hang well on and rig down pulling unit. Bring pump jack to location. Wait on electric hookup and flowline tie in.

RECEIVED
AUG 17 1993
OIL CON. DIV.
DIST. 3

RECEIVED
BLM
AUG 11 AM 9:52
FARMINGTON, NM

14. I hereby certify that the foregoing is true and correct

Signed Reinhold Title Engineer

Date 8-10-93

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

ACCEPTED FOR RECORD

AUG 16 1993

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side
NMOCD

FARMINGTON DISTRICT OFFICE
Sm