rorm 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF	LAND MANAGEMENT		Expires. Ivien	SN 51, 1995
Do not use this form for proposals to	S AND REPORTS ON WELLS drill or to deepen or reentry to a different rest FOR PERMIT - " for such proposels JUII -	3LM ervoir.	Designation and Serial SF-07 ian, Allottee or Tribe N	8040
			nit or CA, Agreement D	esignation
Type of Well Oil Well Gas Well Other Name of Operator	Attention:		Name and No. Mudge LS	#16
Amoco Production Company Address and Telephone No. P.O. Box 800, Denver, Colorado 8020	Gail M. Jefferson, R (303) 830-6157	12350	B. API Well No. 3004510940 10. Field and Pool, or Exploratory Area	
. Location of Well (Footage, Sec., T., R., M., or Survey De		nit B	Fruitl Inty or Parish, State San Juan	and New Mexico
2. CHECK APPROPRIATE I	BOX(s) TO INDICATE NATURE OF	NOTICE , REPORTE OF ACTION	r, or other	DATA
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Non-Rou Water St Conversi Dispose V	struction tine Fracturing nut-Off on to Injection Nater of multiple completion of	on Well Completion or
Amoco Production Company reques	ts permission to plug and abandon the about the service of the ser	830-5578 or Gail Je		
			ECE	70. The second of the second o
4. I hereby certify that the foregoing is true and correct Signed Kull W. Jffer	Sor Title S	r. Admin. Staff Asst.	Date	05-31-1996
Approved by Conditions of approval, if any:	Title		NPP# 0	VED

Title 1B U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictions



Mudge LS #16
Orig. Comp. 8/60
TD = 7580, PBTD 7576
Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 3/8" tbg. Run in hole with tbg and CIBP, set CIBP at 7370'. Test csg integrity to 500#. Spot 100' cement plug on top. (22 cuft cement) Pull up hole and spot 100' cement 6249' to 6349' GP, 4233' to 4333' MV, 3710' to 3810' CK, 2600' to 2500' PC, 2200' to 2300' FT, and 1014' to 1114' KL. (96 cuft cement) RIH with perf and shoot squeeze holes at 250' and circulate to surface. (42 cuft cement) Place cement plug from 250 to surface. (39 cuft cement)
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

To:	Carolanne	Wyett-Amoca
		•

F	Δ
ww.	Unip Harraden
	Chip Harraden Geologist -BLM

Date FAX Sent: 5/17/96 FAX# 303-830-4777

	920 FNL, 1650 FEL Sac 10, 31N-11W G-5902' KB 5913
SanJose	TO 75%0 PATD 7576 SF-078040
A 4	Suctace
Ojo Alamo	Not Present er recognizeable on logs
Kirtland	1064
Fauitiand _	2256'
Pictured Cliffs	2650'
	2822' er 3412'
Cliff House	4283
Menefee	4480'
Point Lookout	4901'
Mancos	5281
Gallup	6299'
Dakota Morrison	7079' 7369 to PBTD
Carolanne	
-ω(11 need a plug @ the top of the Kirtland (1114'to 1)

MUDGE LS 016 1616
Location - 10B-31N-11W
SINGLE MU
Orig.Completion - 8/60
Last Lile Update - 1/89 by DDM

DOT 01 7,625 HLOD CSA 2770 26 TER/IT, J 58 CASING TOC By CBL 8001 HOT OF 2.375 IN OD THG AT 7411

BR--- SPI FERT 7078-1786.

MO--- 2SPF PERF 7428 - 7466 - 7474-- 1497 - 7520--7542 - 7550 - 7570

PBTD AT 7576 FT.

TOTAL DEPTH 7580 FT.

BOT OF 5.5 IN OD CSA 7580 17 LB/HT, J-55 CASING CATHODIC PROTECTION - 7 RECOMP AS SWD 7/88 & ST