50-5 (Jur. 390)

## UNITED STATES

FORM AFPROVED 35

0111125 0171120	· · · · · · · · · · · · · · · · · ·
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	Budget Bureau No. 1004-013 Expires: March 31, 1993

SUNDRY NOTICES AND	REPORTS ON WELLS	5. Lease Designation and Serial No.
Do not use this form for proposals to drill or to		SF078040
Use "APPLICATION FOR PER		6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well		
Oil Sas Other		8. Well Name and No.
2. Name of Operator	Attention:	Mudge A #2
Amoco Production Company	Dallas Kalahar	9. API Well No.
3. Address and Telephone No.	(303) 830-5129	3004510948
P.O. Box 800, Denver, Colorado 80201	(555) 555 5125	10. Field and Pool, or Exploratory Area
4. Location of Well. (Footage, Sec., T., R., M., or Survey Description)		Blanco Mesaverde
660' FNL 660' FEL Sec	. 10 T 31N R 11W	11. County or Parish, State
		San Juan New Mexico
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE,	BEPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
	THEOLACION	14.40.
57	Abandonment	Change of Plans
X ∧otice of Intent	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair  Altering Casing	Water Shut-Off
Final Abandonment Notice	Other Cathodic well abandonment	Conversion to Injection Dispose Water
	(Note: Re	Juspose water  port results of multiple completion on Well Completion or  etion Report and Log form. )
The cathodic protection well associated with In addition, Amoco also requests approval to reclaimed if utilized, upon completion of this process.	construct a temporary 15'x15'x5' blow pit	
ereby certify that the foregoing is true and correct  red  ace for Federal or State office use)	Title Staff Business	APPROVED
		DICTOICT MANAGER

- U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or

-ntations as to any matter within its jurisdiction.

## GROUND BED ABANDONMENT

	WELL NAME: Mudge A #2	
	LOCATION: Sec. 10 T31N R11W	-
1)	Weld 6 m dia. spool with diverter line to p	oit.
2)	MIRU	
3)	Wash in hole with 1 1/4" work string. Circu coke breeze. Pull anodes as they come free to TD 4.	
4)	Pump * sx of neat cement w/ 1/4 lb. sk. Pull out work string.	. Flocele.
5)	Top off hole with cement, set flexible pipe as PxA marker.	
6)	RDMO	91, FEB -3 6.111: 09 070 FARMINGTON, NM
Grou	und Bed Specifications	
TD _	ft.	
Hole	e Dia inches. > UNKNOWN	M 19
Casi	ing Dia inches	
	ing Length ft	
¥	sacks of cement = (dia)2xT.D.x.00693	•
	where dia is in inches,	
	TD is in feet	