

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <u>Aztec Oil and Gas Company</u>	8. FARM OR LEASE NAME <u>Childers</u>
3. ADDRESS OF OPERATOR <u>Drawer 570, Farmington, New Mexico</u>	9. WELL NO. <u>#1</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT <u>Blanco Mesaverde</u>
14. PERMIT NO. <u>890 FSL & 1650 FWL, Sec. 1-31N-11W</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 1-31N-11W</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>6083</u>	12. COUNTY OR PARISH <u>San Juan</u>
	13. STATE <u>New Mexico</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to:

Cut off 2" tubing and pull remainder
Run corrosion log to casing shoe
Squeeze open hole from 5006-5318
Set whipstock at approx 4850 or 4800
Drill 4½" hole with gas to approximate TD of 5320
Run 3½" casing to TD, if no appreciable corrosion 3½" liner to TD
Run Gamma Ray Neutron log, cement bond log
Perf Point Lookout formation, run 1½" tubing.
Put bac k on production

18. I hereby certify that the foregoing is true and correct

SIGNED J. C. Williams

TITLE District Superintendent

DATE 4-29-69

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

