

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Beaver Lodge Oil Corporation			Address 1101 Mercantile Dallas Bldg., Dallas 1, Texas			
Lease McEwen	Well No. 1	Unit Letter	Section 5	Township 31N	Range 10W	
Date Work Performed 1/16/59	Pool Blanco Mesa Verde			County San Juan		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Drilled hole to 7512'. Attempted to log, bridged over; drilled out bridge down to 7512'. Hole caved, left bit, 4 drill collars and 17 joints of drill pipe in hole. Plugged back to 5125; set 4 1/2" liner to 5125 and completed as Mesa Verde hole.

Top of liner 4111'.



Witnessed by Jay J. Harris		Position Consultant		Company Beaver Lodge Oil Corporation	
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY					
ORIGINAL WELL DATA					
D F Elev.	T D 7512	P BTD 5125	Producing Interval 4326 - 4958	Completion Date Put back on line 2/17/59	
Tubing Diameter 32 jts. 2" 130 jts. 2 1/2" EUE	Tubing Depth 5105	Oil String Diameter 4 1/2" liner	Oil String Depth 5125		
Perforated Interval(s) 4954-4944/20; 4908-4826/164; 4446-4406/80; 4354-4326/56					
Open Hole Interval		Producing Formation(s) Mesa Verde			
RESULTS OF WORKOVER					
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl
Before Workover					
After Workover	In process				
OIL CONSERVATION COMMISSION			I hereby certify that the information given above is true and complete to the best of my knowledge.		
Approved by Original Signed Emery C. Arnold			Name 		
Title Supervisor Dist. # 3			Position H. Stewart Bennett General Manager		
Date APR 20 1959			Company Beaver Lodge Oil Corporation		

