

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land	Office	Sant	e F	<u>'0</u>	
Lease No. SF-078215					
Unit.	4/2	Cec.	5	dri	llin
-1.1.	i un			1777	

SUNDRY NOTICES AND REPORTS ON WELLSON,

SUBSEQUENT REPORT OF WATER SHUT-OFF	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
SUBSEQUENT REPORT OF ABANDONMENT.	
SUPPLEMENTARY WELL HISTORY	
Set Long String	X
	SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		Жау с,		
Well No. 1 is locate ST/4 Sec. 6	ed 1650 ft. from ${N \brace S}$ line as	and $\frac{1650}{\text{M}}$ ft. from $\left\{\begin{matrix} \mathbf{E} \\ \mathbf{W} \end{matrix}\right\}$ line of	sec. Ó	
(1/2 Sec. and Sec. No.) Blanco	(Twp.) (Range) ((Meridian)		
(Field)	(County or Subdivision)	(State or Territory)		

The elevation of the derrick floor above sea level is 5933 ft.

DETAILS OF WORK

Ran 140 Jts. 7° 0 rd. J-55 20# and 23# casing landed 4301.20. Comented w/ 5 sax reg. 200 sax bridget, 20 sax deg. Tested 7° casing to 1000# for 30 min. 5-2-5 3

	that this plan of work must receive approval in writin ಾಖರಂ ಾಕುಕಾರಿಯಾಗಿದ್ದು, Inc.	ng by the Geological Survey before operations may be commenced.
	Box 3444	
	Aztec, Hew Mexico	M. E. Makvell By N. 3. Maxwell Jr.
		Title Petroleum Ingineer