

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1650' FNL, 1500' FEL, Sec. 2, T-31-N, R-10-W, NMPM, San Juan County

API # (assigned by OCD)

30-045-11070

5. Lease Number

Fee

6. State Oil & Gas Lease #

7. Lease Name/Unit Name

San Juan 32-9 Unit

8. Well No.

25

9. Pool Name or Wildcat

Blanco Mesaverde

10. Elevation:

Type of Submission

Type of Action

☐ Notice of Intent

☐ Abandonment

☐ Change of Plans

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☒ Other - Pay add and restimulation

13. Describe Proposed or Completed Operations

- 10-6-96 MIRU. ND WH. NU BOP. TOOHH w/2 3/8" tbg. TIH w/5 1/2" csg scraper to 5530'. Blow well & CO. TOOHH. TIH w/CIBP, set @ 5475'. Perf Menefee/Point Lookout @ 5158, 5166, 5207, 5240, 5246, 5271, 5278, 5294, 5298, 5327, 5332, 5359, 5365, 5369, 5407, 5416, 5433, 5437, 5448 w/19 holes total. TIH w/pkr, set @ 5460'. PT CIBP to 3800 psi/15 min, OK. Reset pkr @ 5100'. Acidize w/1500 gal 15% Hcl. TOOHH w/pkr.
- 10-7-96 TIH w/scab lnr & FB pkrs. Isolate Cliff House w/scab lnr. Load tbg & set pkrs. Attempt to retrieving standing valve. TOOHH w/standing valve. TIH w/RBP, set @ 4965'. TOOHH. TIH w/pkr, set @ 60'. Attempt to PT, failed. TIH, reset RBP to 4900'. Reset pkr @ 60'. Put gauge on 5 1/2" csg annulus. Csg leaking. TIH, release RBP, TOOHH. TIH w/5 1/2" pkr, set @ 4958'. Frac Menefee/Point Lookout w/110,000# 20/40 Arizona sd, 3069 bbl slk wtr. TOOHH.
- 10-8-96 Release pkr, TOOHH. TIH w/retrieving tool. Latch scab lnr & pkrs. TOOHH. TIH, blow well & CO.
- 10-9/10-96 Blow well & CO.
- 10-11-96 Blow well & CO. Drill up CIBP @ 5475'. Push junk from CIBP down hole. CO to PBTD @ 5530'. Blow well & CO.
- 10-12-96 Blow well & CO.
- 10-13-96 Blow well & CO. TOOHH w/pkr & RBP. TIH w/pkr & RBP, set RBP @ 5000'. PT RBP to 1000 psi/15 min, OK. Reset pkr @ 4400'. PT csg to 1000 psi, OK. TIH, latch RBP. TOOHH w/RBP & pkr. TIH, blow well & CO.
- 10-14-96 Blow well & CO. TOOHH. TIH w/177 jts 2 3/8" 4.7# J-55 tbg, landed @ 5491'. ND BOP. NU WH. RD. Rig released.

SIGNATURE

Regulatory Administrator October 15, 1996

(This space for State Use)

Approved by ORIGINAL SIGNED BY ERNIE BUSCH

Title

DEPUTY OIL & GAS INSPECTOR, DIST. #3

Date

OCT 17 1996