CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Revised 1-1-89

TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Check for casing leak 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent date, including entimated date of starting any proposed work) SEE RULE 1103. Amoco Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Sr. Staff Admin. Supy. 1972 1/36/90	DISTRICT 1 P.O. Box 1980, Hobba, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088			WELL API NO. 30-045-11080	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOA PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOA PERMIT" (FORM: 10 FOR SUCH PROPOSALS) 1. Type of Well: ORE 2. Name of Operator Annoco Production Company Attn: John Hampton 3. Address of Operator P. O. Box 800 Denver, Colorado 80201 1. Well Locate Usin Letter B: 1190 Feet From The North Line and 1700 Feet From The East Line Section 4. Township 31N Range 10W NMIM San Juan County 10. Elevation (Show whether OF, RRF, RT, CR, ac.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF. PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING OTHER: Check for casing leak Tomes of Operator Themporarily Abandon Company tested the subject well for casing leak as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Rum CBI, from 4240' to surf. (Cood cmt. bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 9023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-9119 if you have any questions. OIL CON. DIV. DIST. 3 1 Durney sendy out the information those is tone and complete to bot of my browbolgs and baild. **The Control of	DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Me:	Santa Fe, New Mexico 87504-2088 wer DD, Artesia, NM 88210			ATE FEE X
Control Use This Form For Proposals To Original On Tool Early Control For Permitty The Proposal of Control For Such Proposals	DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410	•		6. State Oil & Gas Lease N	la.
ONLE TO STAND THE PROPOSED OF COMPANY ALLER AND COMMENCE DELIGIOUS (Clearly state all peribert details, and give perivent dates, including entimated date of staring any proposed world.) 1. Set by @ 4240'. Set pkr @ 4220'. 2. Name of Operator Amoco Production Company Attn: John Hampton Amoco Production Company tested the subject well for casing leaks as follows: 1. Set by @ 4240'. Set pkr @ 4220'. 2. Pr tst by to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CEL To The Production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 I brethy terrify that the Information bow is tow and complete to the boat of my knowledge and belief. OTHER: OTHER: SET. MEMBRANE OF Assume or Wildeau Blanco Messaverde Blanco Messaver	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE "APPLICATION FO	EPEN OR I OR PERMIT	PLUG BACK TO A	7. Lease Name or Unit Agr	recinent Name
Amoco Production Company Attn: John Hampton 3. Addies of Operator P.O. Box 800 Denver, Colorado 80201 4. Weil Location Unit Letter B: 1190 Feet From The North Section 4 Township 31N Range 10W NMFM San Juan County 10. Elevation (Show whether DF, RRB, RT, GR, stc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Check for casing leak 12. Describe Proposed or Completed Operations (Clearly state all perioses details, and give periosen dates, including estimated date of starting any proposed worth) SEE RULE 1103. Amoco Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good emt bond from 4240' to 2950'). 5. Remove pbp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 Ihreby certly had be information doors in time and complete to the best of my knowledge and belief. OTHER: St. Staff Admin. Supply pages.	0.0			Usselman Gas	Com
P.O. Box 800 Denver, Colorado 80201 Blanco Mesaverde 4. Weil Location Unit Letter B : 1190 Feet From The North Line and 1700 Feet From The East Line Section 4 Township 31N Range NMFM San Juan County 10. Elevation (Show whether DF, RRB, RT, GR, atc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DOTHER: Check for casing leak Township SEE RULE 1103. Amoor Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). SEP 2 8 1990 Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 Ibertity certly that be information bove is the and complete to the bot of my knowledge and belief. **The Staff Admin. Suply Not to Supply 10 Media Suply Not to Supply 10 Media Suply Not to Suply 10 Media Suply 10		Joh	n Hampton	1	
Ubit Letter B : 1190 Feet From The North Line and 1700 Feet From The East Line Section 4 Township 31N Range 10W NMFM San Juan County	P.O. Box 800 Denver, Colorado	8020	1		de
Township Range NMFM County			Line and1700	Feet From The	East Line
10. Elevation (Show whether DF, RKB, RT, GR, stc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: Check for casing leak There. Protected Operations (Citarly state all pertinent details, and give pertinent dates, including entinested date of starting any proposed work) SEE RULE 1103. Amoco Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run OBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3	Section 4 Township	Range			County
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Check for casing leak THER: Check for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. ARM CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). Set tbg @ 5023'. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3	10. Elevation (Show w	hether DF,	RKB, RT, GR, esc.)		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: Check for casing leak Amoral Work) SEE RULE 1103. Amoco Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 Thereby certify that the information above is true and complete to the best of my knowledge and belief.	11. Check Appropriate Box to Indi-	cate Nat	ure of Notice, R	eport, or Other Data	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: OTHER: Check for casing leak X 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Amoco Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Sr. Staff Admin. Supy.pur. 2/36/90	NOTICE OF INTENTION TO:		SUB	SEQUENT REPO	RT OF:
CASING TEST AND CEMENT JOB OTHER:	PERFORM REMEDIAL WORK PLUG AND ABANDON	RI	EMEDIAL WORK	ALTER	RING CASING
OTHER:	TEMPORARILY ABANDON CHANGE PLANS	C	OMMENCE DRILLING	G OPNS. PLUG	AND ABANDONMENT
12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Amoco Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 I hereby certify that the information above is true and complete to the best of my knowledge and belief. Order of Head of Table 1972-1972 for Staff Admin. Supplying 1972-1972-1972-1972-1972-1972-1972-1972-	PULL OR ALTER CASING	CASING TEST AND CE		EMENT JOB	
Amoco Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Order of the surface of the best of my knowledge and belief. Order of the surface of the best of my knowledge and belief. Order of the surface of the best of my knowledge and belief.	OTHER:		THER: Check	for casing leak	X
Amoco Production Company tested the subject well for casing leaks as follows: 1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Order of Many 1 Many 1 Many 2 Sr. Staff Admin. Supv. page 9/26/90		sails, and gi	ive pertinent dates, inclu	kling estimated date of starting	g any proposed
1. Set bp @ 4240'. Set pkr @ 4220'. 2. Pr tst bp to 2000#. Held. Pr tst annulas to 750# for 15 min. Held. 3. Remove pkr. 4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 I hereby ceruly that the information above is true and complete to the best of my knowledge and belief. Order of Hereby ceruly that the information above is true and complete to the best of my knowledge and belief.	•	ject w	ell for casi	ng leaks as foll	ows:
4. Run CBL from 4240' to surf. (Good cmt bond from 4240' to 2950'). 5. Remove bp. 6. Set tbg @ 5023'. 7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 Thereby certify that the information above is true and complete to the best of my knowledge and belief. Sr. Staff Admin. Supv. DIV.	 Set bp @ 4240'. Set pkr @ 4220'. Pr tst bp to 2000#. Held. Pr tst 				
7. Return to production 3/9/90. Please call Cindy Burton at 303-830-5119 if you have any questions. OIL CON. DIV. DIST. 3 Thereby ceruly that the information above is true and complete to the best of my knowledge and belief. Sr. Staff Admin. Supv. DIV.	4. Run CBL from 4240' to surf. (Good 5. Remove bp.	emt bo	and from 4240	' to 2950'). (D) E	CEIVEN
Thereby certify that the information above is true and complete to the best of my knowledge and belief. Sr. Staff Admin. Supv. page 9/26/90	7. Return to production 3/9/90.			IN.	ש
Orland Jack Sr. Staff Admin. Supv. 19/26/90	Please call Cindy Burton at 303-830-511	.9 i f y	ou have any	questions. OIL	
Sr. Staff Admin. Supv. DATE 1/26/40					9/01/00
30)-	Kas	TITLE .	Sr. Staff		303-
TYTE OR FRIST NAME John L. Hampton TELEPHONE NO. 830-3023	TYPE OR PRINT NAME JOHN L. RAMP CON			TE	SERIKINE NO. ODO DOGO
(This space for State Use) ATTROVED BY TITLE SUPERVISOR DISTRICT # 3 DATE OCT 0 1 1991			SUPERVISOR DI	STRICT # 3	OCT 0 1 199

•
l