


Form 9-331a
(Feb. 1951)

COPY TO O. C. C.
X



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 67999 079048
Unit San Juan 32-9 Unit
14-08-001-569

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 19, 1953

Well No. 10 is located 1628 ft. from [N] line and 1634 ft. from [E] line of sec. 34.

Section 34 32N 4W N. M. P. M.
(Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6620 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is intended to drill a well through the Mesaverde with rotary tools, drilling the Mesaverde with gas circulation, and to shoot the Mesaverde with two quarts of S.H.G. per foot. Total depth 5960'.

Casing Program:

9-5/8" at 172' with 125 sacks of regular cement circulated to surface.
7" at 5360' with 500 sacks of regular cement.

The E₂ of Section 34 is dedicated to this well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company EL PASO NATURAL GAS COMPANY

Address BOX 397

FARMINGTON, NEW MEXICO

By [Signature]

Title Petroleum Engineer.



1. The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the integrity of the financial system and for the ability to detect and prevent fraud.

2. The second part of the document outlines the specific procedures for recording transactions. It details the steps involved in the accounting cycle, from identifying the transaction to posting it to the appropriate ledger account. It also discusses the importance of double-checking entries to ensure accuracy.

3. The third part of the document addresses the issue of reconciling accounts. It explains how to compare the company's records with the bank's records to identify any discrepancies. It provides a step-by-step guide for performing a bank reconciliation, including how to handle outstanding checks and deposits in transit.

4. The fourth part of the document discusses the importance of internal controls. It describes various control measures that can be implemented to reduce the risk of errors and fraud, such as segregation of duties, authorization requirements, and regular audits. It also discusses the role of management in establishing and maintaining a strong internal control system.

5. The fifth part of the document provides a summary of the key points discussed in the previous sections. It reiterates the importance of accurate record-keeping, proper recording procedures, regular reconciliation, and strong internal controls. It concludes by stating that these practices are essential for the success of any business and for the protection of its assets.