



**NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT**

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178 Fax (505) 334-6170

GARY E. JOHNSON
GOVERNOR

JENNIFER A. SALISBURY
CABINET SECRETARY

January 26, 1996

Dolores Diaz
Meridian Oil Inc
PO Box 4289
Farmington NM 87499

RE: Wells Which Require Retesting

Dear Dolores:

The 1995 Packer Leakage Tests on the following wells indicate communication between the producible zones:

SJ 27-4 Ut #105, G-19-27N-04W, 30-039-21012
SJ 27-4 Ut #13A, O-20-27N-04W, 30-039-20983
SJ 27-4 Ut #120, K-34-27N-04W, 30-039-22122
SJ 27-5 Ut #24A, I-32-27N-05W, 30-039-22310
SJ 27-5 Ut #8, L-32-27N-05W, 30-039-06806
Reid A #1M, J-13-29N-10W, 30-045-24497
Mexico Fed R #1, H-12-31N-13W, 30-045-22126
Susco 16 State #1, M-16-32N-08W, 30-045-25278

To comply with Rule #112A, you are hereby directed to initiate remedial activity and retest the wells.

Sincerely,

Johnny Robinson
Deputy O&G Inspector

JR/sh

cc: Well files