Submit 3 Copies	it 3 Copies propriate Energy, Minerals and Natural Resources Department					Form C-103		
to Appropriate District Office	Ener	rgy, Minerals a	nd Natural Res	sources Department		Kevised 1	-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 P.O.Box 2088						).		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088						3004522221 5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410						STATE FEE X		
1000 RIO Brazos Ru., Aztec,	NM 87410				6. State Oil &	Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						7. Lease Name or Unit Agreement Name Sammons Gas Com /H/		
1. Type of Well:	GAS 🔽		<u></u>			minions Gas Com	/п/	
OIL WELL . Name of Operator	GAS X	OTHER	Attention:		8. Well No.			
Amoco Production Company Dallas Kalahar						1		
3. Address of Operator P.O. Box 800 Denve	r	Colorado	80201		9. Pool name o Bla	or Wildcat anco PC/Blanco M\	/	
4. Well Location Unit Letter P	: 1040	) Feet From The	South	Line and	840 Feet Fr	rom TheEast	Line	
Section	6	Township	31N F	Range 10W	NMPM	San Juan	County	
		10. Elev	ation (Show wheth	her DF, RKB, RT, GR, etc., 5842' GL	)			
<sup>11.</sup> Ch	eck App	ropriate Box	to Indicate	Nature of Notice,	Report, or Ot	her Data		
		ENTION TO:		•	UBSEQUENT I			
PERFORM REMEDIAL WOR	< 🗌 .	PLUG AND ABA		REMEDIAL WORK		ALTERING CASIN	G [_	
TEMPORARILY ABANDON		CHANGE PLANS	s 🗌		G OPNS.	PLUG AND ABANI		
PULL OR ALTER CASING						]		
OTHER: Brad	enhead Re	pair	×	OTHER:	, <u>, , , , , , , , , , , , , , , , </u>			
12. Describe Proposed or Cor work) SEE RULE 1103.	npleted Opera	ations (Clearly state	all pertinent deta	ails, and give pertinent date	s, including estimate	ed date of starting any p	proposed	
Amoco Production C pressure.	ompany in	ntends to perfo	rm the attach	ed workover procedu	ire required to e	liminate bradenhe	ad	
In addition, Amoco a reclaimed if utilized,	-			emporary 15'x15'x5'	_	-		
lf you have any ques		)ECEIV Nov - 2 199						
					0[]	11 GON. D DIN: 3	07.	
I hereby certify that the info		-						
signature <u>Dalla</u>	o Kalc	than /pj	h	Staff Busin	ness Analyst	DATE10-2	5-1994	
TYPE OR PRINT NAME		Dallas Kalahar				TELEPHONE NO. (30	3) 830-512	
(This space for State Use)	JOHNN	NAL SIGNED I NY ROBINSON	d	TITLE DEPUTY OIL & GA	as inspector, d	DIST. #3	2-94	
conditions of approval, if a Notify OCD	ANY:	GAS INSPECT to witness		IIILE		UAIE	- <b></b>	

## Sammons Gas Com H 1 P 06 32N - 10W 30-045-2222100:PC

Bradenhead Procedure October 26, 1994

- 1. Record TP, SICP, and SIBHP.
- 2. MIRUSU.
- 3. TOH with 2 3/8" tubing (check condition of tubing).
- 4. RU lubricator and perforate the PC with 3 1/8" HCP gun, 12.5 g, 120 deg phasing, 2 JSPF..

## Perfs 2610-2680'

- 5. RIH with RBP and set at 2550'.
- 6. Run CBL and fax to Khanh Vu (Denver, 303-830-4276)
- 7. Perforate 2 squeeze holes within 200' of TOC.
- 8. Attempt to circulate to surface, and conduct a cement squeeze with adequate cement. Drill out cement.
- 9. TOH with RBP

- · · · .

- 10. Clean out to PBTD (2759')
- 11. RIH with 2 3/8" tubing.
- 12. Tie well back into surface equipment and turn over to production.