submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	tices and Reports on Wells	~	
		5.	Lease Number
. Type of Well		6.	SF-081155 If Indian, All. or
GAS		0.	Tribe Name
5			ITIDE Name
		7.	Unit Agreement Nam
. Name of Operator	A DEC - 3 Los		Allison Unit
BURLINGTON		SIN o	
BURLINGTON RESOURCES 0IL	& GAS COMPANY	.er	
	Collina Price 20	8.	Well Name & Number
. Address & Phone No. of Opera	ator		Allison Unit #53
PO Box 4289, Farmington, NM	4 87499 (505) 326-9700	9.	API Well No.
			30-045-23134
. Location of Well, Footage, S		10.	Field and Pool
1480'FNL 1800'FEL, Sec.29, 1	[-32-N, R-6-W, NMPM		Blanco Mesaverde
		11.	County and State
			San Juan Co, NM
Subsequent Report	Casing Repair Water	Shut o	
	spinner survey on the subject we		
3. Describe Proposed or Comp	_X_ Other -		
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 58 10
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 58 10
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 58 10
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 58 10
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 58 10
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 FASAANOTON,
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 58 10
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 FASAANOTON,
3. Describe Proposed or Comp It is intended to run a s	_X_ Other -		rding 070 FASAANOTON,
3. Describe Proposed or Comp It is intended to run a s to the attached p	_X_ Other -		rding 070 FASAANOTON,
 3. Describe Proposed or Composed or Composed	_X_ Other -	ll acco:	rding 98 HOV 18 PH 12: 56 070 FARMINGTON, NM
 3. Describe Proposed or Composed or Composed or Composed to run a state to the attached part of the attac	_X_ Other - pleted Operations spinner survey on the subject we rocedure. a foregoing is true and correct. L	ll acco:	rding 98 HOV 18 PH 12: 56 070 FARMINGTON, NM
 3. Describe Proposed or Composed or Composed	X_Other - pleted Operations spinner survey on the subject we rocedure. a foregoing is true and correct.	ll acco:	rding 98 NOV 18 PH 12: 56 911/16/98



Allison Unit #53

Blanco Mesaverde Unit G, Section 29, T32N, R06W San Juan County, New Mexico Elevation 6457' GL, 6468' KB LAT: 36.954346 Long 107.478455

Summary:

The Allison Unit ± 53 was spudded in September of 1978 and was originally completed in the Point Lookout, Menefee, and Cliffhouse. In September of 1997, the Lewis was added. Since 1997, the Mesaverde has been separated from the Lewis by a packer and the Allison Unit #53 has been producing Lewis only up the casing, however the Lewis has loaded up with frac fluid invalidating the production data gathered to date. By pulling the packer and running the spinner flowmeter, the percent contribution of the Lewis and of the individual zones within the Lewis can be determined. The data gathered in this sweep of spinner surveys will be combined with the spinner data gathered in the spring of 1998 to help determine the ideal stimulation design for the Lewis Shale.

Procedure:

1. Comply with all NMOCD, BLM, and BR regulations. Conduct daily safety meetings for all personnel on location.

DO NOT KILL WELL. ANY FLUIDS USED IN WELLBORE WILL INVALIDATE DATA NEEDED. IF FLUIDS ARE REQUIRED, CONTACT MICHELE QUISEL OR STEVE CAMPBELL TO DISCUSS ALTERNATIVES.

- 2. Inspect location and wellhead and install rig anchors prior to rig move if needed.
- 3. MOL, hold safety meeting and RU slickline unit. SI Master valve. ND bullplug on flowtee. RU full lubricator and test to 1500 psi. Open master valve. RIH w/slickline and set tubing choke in FN @ 5961 ' (1.81" I.D. bore). RD slickline unit. SI master valve.
- 4. RU workover unit. Check all safety equipment to insure proper location and working order. ND wellhead and NU 7-1/16" 3M BOP, spool, stripping head and blooie line to pit. Continue to flow well through casing valve. Flow well through casing valve and blow well through blooie line to pit.
- 5. Release the 4-1/2" Baker Model R packer set @ 4904. Strip 195 jts. 2-3/8" 4.7# J-55 tubing and packer through stripping head and stand back. ND stripping head. SI rams on BOP.

THE WELL WILL REMAIN ON PRODUCTION DURING THE ENTIRE SPINNER SURVEY.

Allison Unit #53

Blanco Mesaverde Unit G, Section 29, T32N, R06W San Juan County, New Mexico Elevation 6457' GL, 6468' KB LAT: 36.954346 Long 107.478455

- 6. RU Schlumberger. RU full lubricator and test to 1500 psi. Open rams on BOP and RIH w/ spinner flowmeter tool/GR/CCL. Correlate depth to GR/CCL logs provided by the engineer on location.
- 7. Take spinner survey readings at the following stations:

• Station #1	4380'	Top of Navajo City Chacra
• Station #2	4675'	Top of Otero Chacra
• Station #3	4810'	Top of the Middle Bench of the Otero Chacra
 Station #4 	5488'	Top of Massive Cliffhouse (Mesaverde)

- 8. Tag bottom w/ spinner tool. POOH w/ spinner flowmeter tool/GR/CCL and SI rams on BOP. RD full lubricator. RD and release Schlumberger.
- 9A. If fill, TIH w/ 3-7/8" bit and CO to PBTD. TOOH.
- 9. NU stripping head. Open rams on BOP. Strip 195 jts. 2-3/8" 4.7# J-55 tubing w/ expendable check and seating nipple one joint off bottom and land tubing @ 5990'. Pump off expendable check. ND stripping head, BOP, and blooie line. NU wellhead. RD and release rig.
- 10. NU bullplug and flowtee. Open master valve and put well on production.