

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☐ gas well ☒ other

El Paso Natural Gas Company

Box 289, Farmington, New Mexico 87401

AT SURFACE: 1840'N, 1500' E

AT TOTAL DEPTH:

SUBSEQUENT REPORT OF:

(other)

RECEIVED

MAR 02 1966

U. S. GEOLOGICAL SURVEY,
FARMINGTON, N. M.

100 (NOTE: Report results of multiple completion for
change on Form 9-330) MAR 3 1982

OIL CON. COM.
DIST. 3

In order to permanently repair the casing failure in this well, it is intended to set a drillable bridge plug above the perforations, cut off the casing above top of cement, replace the bad joints of casing and tie back into the casing stub with a Bowen Casing Patch. Cement new pipe back to the surface. Following casing repair, the bridge plug will be drilled out and the well returned to production.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Drilling Clerk DATE March 2, 1982

APPROVED BY J. H. Kelly TITLE _____ DATE _____
CONDITIONS OF APPROVAL MAR 1987

For JAMES F. SIMS
DISTRICT ENGINEER

NMOCCH