Form 9-331						
(May 1963)	DEDARTMENT	ED STATES	SUBMIT IN TRIPLE	ICATE•	Form approved. Budget Bureau No. 4	19 . 19 4 4 10 4
	_	OF THE INTER	(IOK verse side)	5. LEASE	DESIGNATION AND SEI	RIAL NO.
		GICAL SURVEY		N14/01	614	
(Do not use this fo	PRY NOTICES A orm for proposals to di Use "APPLICATION F	AND REPORTS rill or to deepen or plug OR PERMIT—" for such	ON WELLS back to a different reservoir. proposals.)	6. IF IND	IAN, ALLOTTEE OR TRI	BE NAME
OIL GAS WELL OTHER 2. NAME OF OPERATOR					7. UNIT AGREEMENT NAME	
Southland Royalty Company				8. FARM (OR LEASE NAME	
3. ADDRESS OF OPERATOR					Thompson	
P. O. Drawer 570, Farmington, NM 87401				į.	9. WELL NO.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				#2-A		
At surface					10. FIELD AND POOL, OR WILDCAT	
960' F	NL & 1070' FE	L		11. SEC.,	O Mesa Verde	
14. PERMIT NO.				Section	on 28, T31N,	הזיר וכו
TERMIT NO.	15. ELE	EVATIONS (Show whether by 6171' (12. COUNT San Ju	Y OR PARISH 13. ST.	LTE
6.	Check Appropria	te Box To Indicate N	Nature of Notice, Report			Mexico
Nor	TICE OF INTENTION TO:	io zon io malcale i				
TEST WATER SHUT-OFF	<u> </u>	[s	UBSEQUENT REPORT	OF:	
FRACTURE TREAT	1 1	COMPLETE	WATER SHUT-OFF		REPAIRING WELL	
SHOOT OR ACIDIZE	ABANDON*		FRACTURE TREATMENT		ALTERING CASING	
REPAIR WELL	CHANGE PI	LANS	SHOOTING OR ACIDIZIN	duction Tub	ABANDONMENT*	V
		[]	(Nome Desert	**************************************		<u>X</u>]
(Other) 7. DESCRIBE PROPOSED OR CO proposed work. If we nent to this work.) *	MPLETED OPERATIONS (ell is directionally drill	Clearly state all pertinen led, give subsurface locat	- Completion of the	scombission Reboil	and Log form	ing any
7. DESCRIBE PROPOSED OF CO proposed work. If we nent to this work.) * 1-27-79 Ran		£ 2 3/8", 4.7#.	Completion or R t details, and give pertinent tions and measured and true	dates, including es vertical depths for	and Log form.) timated date of start all markers and zon	ting any
17. DESCRIBE PROPOSED OF CO proposed work. If we nent to this work.) *	162 joints of	£ 2 3/8", 4.7#.	t details, and give pertinent tions and measured and true	dates, including es vertical depths for	and Log form.) timated date of start all markers and zon 5134.78'	1979 20M.
7. DESCRIBE PROPOSED OR COproposed work. If we nent to this work.) * 1-27-79 Ran land I hereby certify that the SIGNED	162 joints of ded at 5146.78	E 2 3/8", 4.7#,	t details, and give pertinent tions and measured and true J-55, EUE tubing	dates, including es vertical depths for Total of	simated date of start all markers and zon 5134.78' FEB 1 OIL CON. (DIST.)	1979 20M.
7. DESCRIBE PROPOSED OR COproposed work. If we nent to this work.) * 1-27-79 Ran land	162 joints of ded at 5146.78	E 2 3/8", 4.7#,	t details, and give pertinent tions and measured and true J-55, EUE tubing	dates, including es vertical depths for Total of	simated date of start all markers and zon 5134.78' FEB 1 OIL CON. (DIST.)	1979 20M.
7. DESCRIBE PROPOSED OR COproposed work. If we nent to this work.) * 1-27-79 Ran land I hereby certify that the SIGNED	162 joints of ded at 5146.78	E 2 3/8", 4.7#,	t details, and give pertinent tions and measured and true J-55, EUE tubing	dates, including es vertical depths for Total of AN 3 1979 GEOLOGICAL SU Manager Manager Manager	simated date of start all markers and zon 5134.78' FEB 1 OIL CON. (DIST.)	1979 COM. /

*See Instructions on Reverse Side

MYNICO