Form 9-331

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	USA-SF-078095
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
CUMPRY NOTICES AND DEPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or plug back to a different	- STEEL THE
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas XX other	Case A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
2. NAME OF OPERATOR	
Tenneco Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
720 S. Colo. Blvd., Denver, CO 80222  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 무료명을 및 명품일을
below.) 860'FNL, 790'FWL, Unit D	Sec. 19; T31N; R11W
AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. (10 10 10 10 10 10 10 10 10 10 10 10 10 1
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	6056'GL 원칙구를 보고 함께 기계
REQUEST FOR APPROVAL TO:  SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF  FRACTURE TREAT	ingress had been seen as a
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE 🗍 💛 🖾 S. GEOLOGICAL Succe	
CHANGE ZONES U FARMINGTON, N. M.	
ABANDON* (other) Status Report: Completion	State of the state
	<u> </u>
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent.	irectionally drilled, give subsurface locations and
	L to this work.)
3/4-3/12/80 MIRUCU 3/4/80. Tag cmt @ 7005'. Ran GR/CCL, c	ement bond good over Dakota
interval. TOC: 5150'. Tested csg to 3500#-hel	
500 gal 7½% DI HCI. Perf'd Dakota @ 7034-381,	
7190-92, 7208-12, w/2SPF (144 holes) Broke do	
gal HCL & 216 balls. Frac'd w/81,300 gal 1% k	
gel & carrying 80000# 20/40 sand, and 25000#	
7041. NDBOP. Kicked well w/ N2. Released rig	3/12/80. <b>24 ETV LD</b> 30 8 B
	in observations of the second
	<b>6 6 2 5 1980</b> \$ 3 \$ 3
	TO SOME CHAMPED TO SOME
	OF TOTAL
Subsurface Safety Valve: Manu. and Type	
18. I hereby Cartify that the foregoing is true and correct	the second secon
SIGNED LILLY MATTER Admin. Super	Visor 75.3/17/80 2022
(This space for Federal or State of	ice use)
APPROVED BY TITLE	DATE TO THE TOTAL OF THE PARTY
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	

NMOCC

a elda 💢