## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		ces and Reports				
				101,411	Lease Number SF-081155	
. Type of Well GAS			PECEWES:		If Indian, All Tribe Name	ll. or
Name of Opera	ator		UE BEC 1 4 19:	$\mathcal{B}$	Unit Agreement Allison Unit	t Name
BURLIN		(	OUL COM, E	) (fill to		
RESOU.	PCFC	GAS COMPANY	Disti. B	心心。		
				8.	Well Name & Nu	umber
	one No. of Operat		****		Allison Unit #	#118
PO Box 4289	, Farmington, NM	87499 (505) 32	26-970 <b>0</b>	9.	API Well No. 30-045-27131	
Location of	Well, Footage, Se	c., T, R, M		10.	Field and Pool	1
	5'FWL, Sec.28, T-		мрм ⊱		Basin Fruitlar County and Sta San Juan Co, N	nd Coa ate
. CHECK APPRO	PRIATE BOX TO IND	CICATE NATURE OF	F NOTICE, REPORT	, OTHER	DATA	
Type of Subm			pe of Action			
Noti	ce of Intent	Abandonmer Recomplet:				
		RECOUNTER				
v Subs	emient Penort	Plugging F	ion New C			
_X_ Subs	equent Report	Plugging H	Back Non-R	outine F	Fracturing	
<u> </u>	equent Report	Plugging F	Back Non-F pair Water	outine F	Fracturing Ef	
	_	Plugging F Casing Rep Altering (	Back Non-R	loutine F Shut of ersion to	Fracturing Ef	
Fina	l Abandonment	Plugging N Casing Rep Altering ( X Other - L:	Back Non-F pair Water Casing Conve iner installation	loutine F Shut of ersion to	Fracturing Ef	
Fina	_	Plugging N Casing Rep Altering ( X Other - L:	Back Non-F pair Water Casing Conve iner installation	loutine F Shut of ersion to	Fracturing Ef	
Fina	l Abandonment	Plugging Notes   Casing Report   Altering ( X_ Other - Little   Leted Operations	Back Non-F pair Water Casing Conve iner installation	Coutine F Shut of ersion to on	Fracturing Ef	
Fina	l Abandonment  Proposed or Compl  MIRU. TOOH w/pun	Plugging Notes of Casing Report   Casing Report   Altering Country   X Other - Little   Leted Operation   The Case of Casing Report   The Casing R	Back Non-F pair Water Casing Conve iner installation   B  H. NU BOP. SDON.	Coutine For Shut of ersion to	Fracturing  If  Injection	ing
Final  Describe  11-12-99 11-13-99	Proposed or Compl  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327	Plugging Notes of Casing Report Altering Control Casing Report Altering Control Casing Report Altering Control Casing Report Action Casing Report Cas	Back Non-F pair Water Casing Conve iner installation  B H. NU BOP. SDON. t tbg @ 3274'. The	coutine If Shut of ersion to on COOH w/th	Fracturing  If Injection  On Injection  On Injection	ing
Final  Describe  11-12-99 11-13-99  11-14-99 11-15/18-99	Proposed or Compl  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD	Plugging Factoring Casing Rep Altering Casing Rep Casing Rep Altering Casing Rep Casing	Back Non-Frair Water Casing Converiner installations  H. NU BOP. SDON. t tbg @ 3274'. The fishing tool	COOH w/th	Fracturing  If Injection  Og. TIH w/fishi	•
Final  Describe  11-12-99 11-13-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH @ 3258'. Lnr p	Plugging Factoring Casing Rep Casing Rep Altering Co X Other - L:  Leted Operations The Arods. ND WI Compared to Market Casing The Arods of Table 1 (1) The Arods of Table	Back Non-Frair Water Casing Converiner installations  H. NU BOP. SDON. t tbg @ 3274'. The fishing tool	COOH w/th	Fracturing  If Injection  Og. TIH w/fishin  W/bit. SDON.  @ 3414'. Lnr t	top
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH	Plugging Factoring Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Casing Casin	Back Non-Frair Water Casing Convert iner installation  B H. NU BOP. SDON. t tbg @ 3274'. The fishing tool 5.5# K-55 LT&C of 1-3412' across of 1-	COOH w/th	Fracturing  If Injection  Og. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To	то <b>р</b> ГІН
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH @ 3258'. Lnr p w/perf mill. S Mill perf plugs J-55 tbg, set	Plugging Factoring Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Casing Repair Casing Cas	Back Non-Frair Water Casing Convert iner installation  B H. NU BOP. SDON. t tbg @ 3274'. The fishing tool 5.5# K-55 LT&C of 1-3412' across of 1-	COOH w/th	Fracturing  If Injection  OG. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To	сор ГІН 7#
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH @ 3258'. Lnr p w/perf mill. S Mill perf plugs	Plugging Factoring Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Casing Repair Casing Cas	Back Non-F pair Water Casing Conve iner installation  H. NU BOP. SDON. t tbg @ 3274'. T  h & fishing tool 5.5# K-55 LT&C of '-3412' across of TOOH w/mill. Ti	COOH w/th	Fracturing  If Injection  OG. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To	сор ГІН 7#
Final  Describe  11-12-99 11-13-99  11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH @ 3258'. Lnr p w/perf mill. S Mill perf plugs J-55 tbg, set	Plugging Factoring Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Casing Repair Casing Cas	Back Non-F pair Water Casing Conve iner installation  H. NU BOP. SDON. t tbg @ 3274'. T  h & fishing tool 5.5# K-55 LT&C of '-3412' across of TOOH w/mill. Ti	COOH w/th	Fracturing  If Injection  OG. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To	сор гін 7#
Final  Describe  11-12-99 11-13-99  11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH @ 3258'. Lnr p w/perf mill. S Mill perf plugs J-55 tbg, set	Plugging Factoring Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Casing Repair Casing Cas	Back Non-F pair Water Casing Conve iner installation  H. NU BOP. SDON. t tbg @ 3274'. T  h & fishing tool 5.5# K-55 LT&C of '-3412' across of TOOH w/mill. Ti	COOH w/th	Fracturing  If Injection  OG. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To	сор гін 7#
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH @ 3258'. Lnr p w/perf mill. S Mill perf plugs J-55 tbg, set	Plugging Factoring Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Altering Casing Repair Casing Repair Casing Cas	Back Non-F pair Water Casing Conve iner installation  H. NU BOP. SDON. t tbg @ 3274'. T  h & fishing tool 5.5# K-55 LT&C of '-3412' across of TOOH w/mill. Ti	COOH w/th	Fracturing  If Injection  OG. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To	сор ГІН 7#
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH @ 3258'. Lnr p w/perf mill. S Mill perf plugs J-55 tbg, set	Plugging Notes and Plugging Notes and Particular Country of the Partic	Back Non-Frair Water Casing Convertiner installation  H. NU BOP. SDON.  t tbg @ 3274'. The fishing tool  5.5# K-55 LT&C of '-3412' across of TOOH w/mill. The NU WH. TIH w/po	COOH w/th	Fracturing  If Injection  OG. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To	сор ГІН 7#
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340   tools. SDON.  Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH   @ 3258'. Lnr p   w/perf mill. S Mill perf plugs   J-55 tbg, set   OK. RD. Rig re	Plugging Notes and Plugging Notes and Particular Country of the Partic	Back Non-Frair Water Casing Convertiner installation  H. NU BOP. SDON.  t tbg @ 3274'. The fishing tool  5.5# K-55 LT&C of '-3412' across of TOOH w/mill. The NU WH. TIH w/po	COOH w/th	Fracturing  If Injection  OG. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To	сор ГІН 7#
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340   tools. SDON.  Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH   @ 3258'. Lnr p   w/perf mill. S Mill perf plugs   J-55 tbg, set   OK. RD. Rig re	Plugging Factoring Casing Rep Altering Casing Rep Casing Rep Casing Rep Altering Casing Rep Casing Rep Altering Casing Rep Casing Rep Altering Casing Rep Casing Rep Casing Rep Altering Casing Rep Casing Rep Altering Casing Rep Casing Rep Casing Rep Altering Casing Rep Ca	Back Non-Frair Water Casing Convertiner installation  H. NU BOP. SDON.  t tbg @ 3274'. The fishing tool  5.5# K-55 LT&C of '-3412' across of TOOH w/mill. The NU WH. TIH w/po	COOH w/th	Fracturing  If Injection  Og. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To pump and	top FIH 7# action
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99  11-20-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340 tools. SDON. Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH @ 3258'. Lnr p w/perf mill. S Mill perf plugs J-55 tbg, set OK. RD. Rig re	Plugging Factoring Casing Rep Altering Casing Rep Market Casing Rep Altering Casing Rep Market Casing Rep Altering Casing Rep Market Casing Re	Back Non-Frair Water Casing Conversioner installations  H. NU BOP. SDON. t tbg @ 3274'. The fishing tool 5.5# K-55 LT&C of '-3412' across of TOOH w/mill. The NU WH. TIH w/purue and correct	COOH w/th	Fracturing  If Injection  Og. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To pump and	top FIH 7# action
Final  Describe  11-12-99 11-13-99 11-14-99 11-15/18-99 11-19-99  11-20-99	Proposed or Complement  MIRU. TOOH w/pun Tbg stuck @ 3340   tools. SDON.  Latch fish @ 327 Circ & CO to TD TOOH w/bit. TIH   @ 3258'. Lnr p   w/perf mill. S Mill perf plugs   J-55 tbg, set   OK. RD. Rig re	Plugging Factoring Casing Rep Altering Casing Rep Market Casing Rep Altering Casing Rep Market Casing Rep Altering Casing Rep Market Casing Re	Back Non-Frair Water Casing Conversioner installations  H. NU BOP. SDON. t tbg @ 3274'. The fishing tool 5.5# K-55 LT&C of '-3412' across of TOOH w/mill. The NU WH. TIH w/purue and correct	COOH w/th	Fracturing  If Injection  Og. TIH w/fishing  W/bit. SDON.  @ 3414'. Lnr tervals. TOOH. To the pump and the pu	top FIH 7# action

Smm United