State of New Mexico Form C-103 Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-045-30889 District II OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III STATE | FEE X 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Culpepper Martin 1. Type of Well: Oil Well Gas Well X Other 2. Name of Operator 8. Well No. ENERGEN RESOURCES CORPORATION 3. Address of Operator 9. Pool name or Wildcat 2198 Bloomfield Highway, Farmington, NM 87401 Blanco Mesaverde 4. Well Location 1900 2200 _ feet from the_ North Unit Letter feet from the line and line 07 Section Township 31N Range 12W NMPM County San Juan 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 5866' GR 11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT** PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION CEMENT JOB OTHER: Add Menefee Sands X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. It is intended to add the Menefee sands as follows:

- 1. MIRU. TOH with tubing.
- 2. Set RBP at 4520'. Test casing to 3000 psi.
- 3. selectively perforate Menefee from 4230-4505. Fracture treat with 60Q foam.
- 4. TIH and clean out with air mist. Retrieve RBP.
- 5. TIH and clean out to PBTD. Land tubing at 4800'. Return to production

3. Till and Cream out to FBTD. Land tubing at 4	toou . Return to production.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Viali' Day			
SIGNATURE 1100 DOMAGNUT	_ TITLE Production Assistant	DATE _	9/16/02
Type or print name Vicki Donaghey		Telephone No.	505-325-6800
(This space for State use)	Committee and the control of the	3 0.	· · · · · · · · · · · · · · · · · · ·
APPROVED BY Conditions of approval, if any:	_ TITLE	DATE	
Conditions of approval, it any.			