



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 678311  
Unit Cundiff

SUNDRY NOTICES AND REPORTS ON WELLS

|  |  |                                     |
|--|--|-------------------------------------|
| NOTICE OF INTENTION TO DRILL                   | SUBSEQUENT REPORT OF WATER SHUT-OFF        |                                     |
| NOTICE OF INTENTION TO CHANGE PLANS            | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |                                     |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     | SUBSEQUENT REPORT OF ALTERING CASING       |                                     |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |                                     |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        | SUBSEQUENT REPORT OF ABANDONMENT           | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    | SUPPLEMENTARY WELL HISTORY                 |                                     |
| NOTICE OF INTENTION TO ABANDON WELL            |  |                                     |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 21, 1958

Well No. 3 is located 1000 ft. from S line and 1600 ft. from W line of sec. 18  
SW Sec. 18 32N 12W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Blanco San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6035 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

On April 19 & 20, 1958. Total depth 3642'.  
This well was plugged and abandoned as follows:

1. Squeezed Point Lookout perforations at 3404 - 3610' with 40 sacks cement.
2. Cut off 7 5/8" casing at 2350', recovered 57 joints (2340').
3. Set cement plug at 2450' - 2550' with 25 sacks (top of casing).
4. Set cement plug at 850' - 950' with 43 sacks (Pictured Cliffs formation).
5. Set cement plug at 450' - 550' with 43 sacks (Fruitland formation).
6. Set cement plug from 55' to surface with 24 sacks.
7. Set 4" pipe 4' high as permanent marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By Original Signed D. G. Johnston

Title Petroleum Engineer