

|                        |  |  |
|------------------------|--|--|
| NO. OF COPIES RECEIVED |  |  |
| DISTRIBUTION           |  |  |
| SANTA FE               |  |  |
| FILE                   |  |  |
| U.S.G.S.               |  |  |
| LAND OFFICE            |  |  |
| OPERATOR               |  |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |  |
|---|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>   | 7. Unit Agreement Name                           |
| 2. Name of Operator<br><b>Walker Bros. Oil Co.</b>  | 8. Farm or Lease Name<br><b>Santa Fe</b>         |
| 3. Address of Operator<br><b>P. O. Box 18715, Okla. City, Okla.</b>   | 9. Well No.<br><b>2</b>                          |
| 4. Location of Well<br>UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM<br>THE <b>East</b> LINE, SECTION <b>7</b> , TOWNSHIP <b>17N</b> , RANGE <b>8W</b> NMPM. | 10. Field and Pool, or Wildcat<br><b>Wildcat</b> |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br><b>6908 KB</b>   | 12. County<br><b>McKinley</b>                    |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 1612': 6 3/4" hole size.  
Proposed: 100' plug; 20 sx- 1612- 1512  
50' plug; 10 sx, 400-450  
40' plug; 8 sx, 90-130  
10' plug at top with 4" iron marker in top.  
Clean up location and fill in pits.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE **Geologist** DATE **May 17, 1965**

APPROVED BY [Signature] TITLE [Signature] DATE 5-17-65

CONDITIONS OF APPROVAL, IF ANY: