

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-55

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.		
7. Unit Agreement Name		
8. Farm or Lease Name		
John Bergin		
9. Well No.		
1		
10. Field and Pool, or Wildcat		
Pleasant - Farmington		
12. County		
San Juan		

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator McCoy & Phillips Bedford, Inc. Agent for & State of New Mexico
3. Address of Operator P.O. Box E, Farmington, New Mexico 87401
4. Location of Well UNIT LETTER <u>F</u> <u>2515</u> FEET FROM THE <u>N</u> LINE AND <u>1410</u> FEET FROM THE <u>W</u> LINE, SECTION <u>21</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned as follows:

8-15-78 Move in rig, rig up, dug pit, hit water @4'
Ran 1 jt. 2 3/8" tbg & tagged plug @ 15'
8-16-78 Cut surface casing off 3' under surface
rig down, fill pit.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry A Bedford TITLE Agent for State DATE 8-31-78
APPROVED BY AR Kendrick TITLE Assistant Secretary DATE 9-1-78
CONDITIONS OF APPROVAL, IF ANY: