

COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Hare	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
12. County	
San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator
	Bedford, Inc. agent for State of New Mexico
3. Address of Operator	
	P. O. Box E, Farmington, New Mexico 87401
4. Location of Well	
UNIT LETTER C 175 FEET FROM THE N LINE AND 1570 FEET FROM	
THE W LINE, SECTION 22 TOWNSHIP 29N RANGE 11W NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned as follows:

- 9-26-78 Move in, rig up, found tbq. parted top of fish @ 14'
- 9-27-78 Pull 1/2" rods out of hole. Go in hole w/over shot couldn't get fish
- 9-28-78 Go in hole w/over shot catch fish. Pull tbq. Ran EUE tbq. in hole tag bottom
- 9-29-78 Spot 30 sx plug 700' to 525'. Perf 4 holes @ 200', cement w/35 sx from 200' to 100' inside & outside casing.
- 9-30-78 Set P & A marker & clean loc.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry G. Bedford TITLE Agent for Operator DATE 11-27-78

APPROVED BY AK Kendrick TITLE SECRETARY DATE NOV 30 1978

CONDITIONS OF APPROVAL, IF ANY: