

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. 14-20-604-1892
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Mountain Tribe
3. ADDRESS OF OPERATOR P. O. Box 480, Farmington, New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 815' FNL and 910 FNL		8. FARM OR LEASE NAME Ute Mountain Tribal "E"
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5587 (RDB)		10. FIELD AND POOL, OR WILDCAT Verde Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NW/4 NW/4 Section 26, T-31-N, R-15-W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As a result of the above well ceasing to produce oil in commercial quantities, we propose to plug and abandon it as follows:

1. Pump 50 sacks cement down 5-1/2" casing with cementing plug, leaving cement plug about 2600'. (44' above top perms. Casing Volume - 30 sacks, leaving 20 sacks squeezed into formation).
2. Pump 45 sacks cement down 5-1/2" - 9-5/8" casing annulus. (about 190' fill).
3. Remove well head and surface equipment.
4. Spot 5 sacks cement for surface plug (0-40') and erect abandonment marker.

Approval to plug and abandon subject well received from USGS on January 27, 1965, Jerry Long to F. H. Hollingsworth.

18. I hereby certify that the foregoing is true and correct

Fred L. Nabors, District Engineer

SIGNED

TITLE

DATE January 28, 1965

(This space for Federal or State signature only)

TITLE

DATE

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JAN 20 1965

JERRY W. LONG
DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
FEB 1 1965
OIL CON. COM.
DIST. 3

RECEIVED

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.