

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

5. LEASE DESIGNATION AND SERIAL NO.

SF 06555 7

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
Producing Royalties Inc

3. ADDRESS OF OPERATOR
Box 1071 Lubbock, Texas 79408

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

990 FNL # 990 FEL Sec. 11
T29N, R12W, SAN JUAN Co. N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5789

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carol Cornell

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 11, T29N R12W NMPM

12. COUNTY OR PARISH

SAN JUAN

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

FULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

☐
☒
☒
☐

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been Plugged & ABANDONED as follows:
4-6-76 Moved in equipment. Pick up 2 5/8" tbg
Ran tbg to TD. Spot 80sx cement Plug
from 4495' to 4060'. Pulled tbg.
4-7-76 Set casing jacks. Work casing.
4-8-76 Shot 7" casing off @ 1998'
Pull casing.
4-9-76 Ran tbg to 2100', Spot 80sx Plug
from 2100 to 1800'; Pull tbg to 750'
4-10-76 Spot 50sx Plug from 50 to 600'
Install P.A. marker w/ 10sx Surface Plug.
Clean loc.

18. I hereby certify that the foregoing is true and correct

SIGNED

Larry H. Beiford

TITLE

Agent for Operator

DATE

4-24-78

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

U. S. GEOLOGICAL SURVEY